



447 K 1-17-18 Cor



OFFICE COPY

Timothy H. Lim, PS
Date 12/14/17

LEGEND

- | | |
|--------|---|
| ● | Iron Pin Set, 5/8" rebar |
| ● | Iron Pin Found, 5/8" rebar |
| ▲ | PK Nail Set |
| △ | PK Nail Found |
| ● | Pipe Found |
| P.O.B. | Place of Beginning |
| Ⓐ | aluminum capped pin 'ODOT R/W District 5' |
| Ⓑ | plastic capped pin 'Baseline Surveying' |

Bearings are based on the Ohio State Plane Coordinate System, NAD83, South Zone, Grid South, as per GPS observations made 12/12/17.

All of: 85-39-03-13-000 (Lot 9	±0.137 ac.)
All of: 85-39-03-14-000 (Lot 10	±0.138 ac.)
All of: 85-39-03-15-000 (Lot 11	±0.130 ac.)
All of: 85-39-03-16-000 (Lot 12	±0.071 ac.)
All of: 85-39-03-07-000 (Lot 38	±0.113 ac.)
All of: 85-39-03-06-000 (Lot 37	±0.140 ac.)
All of: 85-39-03-05-000 (Lot 36	±0.176 ac.)
Port of: 85-39-03-04-000 (Lot 35	±0.069 ac.)
Port of: 85-39-03-03-000 (Lot 34	±0.031 ac.)



Linn Engineering, Inc.
Civil Engineering Consultants
P.O. Box 2086 Zanesville, Ohio 43702-2086
740-452-7434