

Roy Fisher

COPY parcel #'s 02-40-17-11
02-40-17-12 ✓

5185 Edgemoor Road

• ~ Existing Iron Pin

⊙ ~ Iron Pins Set (3/4" d. pipe)

△ ~ Existing Stone

Bearings are based on the previous
survey of 20,000± Ac. (Vol. 803 Pg. 259)

OFFICE COPY
NOT RECORDABLE

W. J. Moran
Vol. 803 Pg. 259
20,000± Ac.

5.86° 57' 44" E.
325.77'
Northeast
Corner of the South-
West Qtr. of Section
17

