727 Cambridge Road Coshocton, Ohio 43812



(614) 623-0993 1-800-842-3264

Paul P. Zigo 10.510 Acres JC071197PG3

Being 10.510 acres, more or less (all of #17-77-04-36, #17-77-04-37, #17-77-04-35-001) in the south half of the fourth quarter of township 1 north, range 8 west, United States Military Lands, in the township of Falls, in the county of Muskingum, in the State of Ohio, and more particularly described as follows:

Commencing at a 3/4" pipe found at the northwest corner of Lot 17, Locust Springs Subdivision, Plat Book 7, page 59, thence, N.13°16'00"E. 30.82' to a point in the centerline of SR 146, Newark Road;

thence, along the centerline of SR 146, Newark Road, N.63°30'00"W. 905.90' to a point, said point being the TRUE POINT OF BEGINNING;

thence, along the property line of James L. & Betty Grosscup, 1096/475, the following 2 courses:

1. thence, S.13°16'00"W. 30.82' to a 5/8" steel pin found;

2. thence, continuing S.13°16'00"W. 793.68' to a 5/8" steel pin found;

thence, along the fence line between Paul P. Zigo and: James L. & Betty Grosscup, Gary F. & Charlotte McGuire, Fountain R. & Jaynellen B. Sharp the following 3 courses:

- thence, S.28°14'07"E. 146.90' to a 5/8" steel pin set;
 thence, S.26°26'59"E. 288.59' to a 5/8" steel pin set;
- 3. thence, along the extension of the fence line and continuing S.26°26'59"E. 102.76' to a point in the Licking

thence, along the centerline of the Licking River the following 5 courses:

- 1. thence, S.75°14'07"W. 129.58' to a point;
- thence, S.85°19'14"W. 71.23' to a point;
- thence, S.78°06'49"W. 252.66' to a point;
- 4. thence, N.62°03'59"W. 226.75' to a point;
- 5. thence, N.39°48'05"W. 60.20' to a point;

thence, along the property line of Ralph Daniel & Mary Ann Thornton, 1069/143 the following 3 courses:

- 1. thence, N.06°35'49"E. 82.25' to a 5/8" rebar of record;
- thence, continuing N.06°35'49"E. 55.11' to a stone found;
- thence, N.05°31'19"E. 750.76' to a corner post;

thence, along the fence line between Paul P. Zigo and: Ralph W. & Florence H. Dingey, John A. Collins & Esther E. Frazier, Ray L. Baldner the following 3 courses:

- 1. thence, S.38°54'13"E. 113.30' to an axle found;
- 2. thence, S.40°14'53"E. 202.70' to an axle found;
- thence, S.37°37'45"E. 137.30' to a 5/8" rebar found;

thence, along the property line of Ray L. Baldner, 1066/522 the following 5 courses:

- 1. thence, N.12°39'50"E. 128.77' to a 5/8" steel pin set;
- thence, continuing N.12°39'50"E. 193.61' to a 5/8" steel pin set;
- 3. thence, continuing N.12°39'50"E. 200.00' to a 5/8" steel pin set;
- thence, continuing N.12°39'50"E. 200.00' to an axle found;
- thence, continuing N.12°39'50"E. 30.32' to a point in the centerline of SR 146, Newark Road;

thence, along the centerline of SR 146, Newark Road the following 2 courses:

- 1. thence, S.61°30'29"E. 38.56' to a point;
- thence, S.63°30'00"E. 61.38' to the TRUE POINT OF BEGINNING, containing 10.510 acres, more or less, including public road right-of-way and is subject to all easements, rights-of-way, or restrictions, whether recorded or implied.


Bearings are based on D.B. 1096/475 and are for angular calculations only. All 5/8" steel pins set are 30" long with plastic cap marked "E.R.D. 7142".

Pertinent documents: tax maps; deeds: 1069/493, 631/264, 997/345, 1066/522, 465/164, 783/125, 1118/321, 1096/475, 1102/135; Plat Book 7, page 59; surveys by: John R. Marshall, Robert B. Pinnick, L. Peter Dinan, Earl

1096-471 Prior deed: 465/164, 1102/135, (PLEASE INSERT DEED BOOK & PAGE, TRANSFER OF 0.004 ACRE FROM GROSSCUP).

war of our Lors could be received and ninety-seven. Description and plat by Landmark Surveys Fat Condition Propremises in the month of October, in the year of our LOFO ONE

DESCRIPTION APPROVED AUDITORS TRANSFER



.