

Re-Survey of Fracker Farm LLC, Exhibit B, in Highland Township, Muskingum County

Situated in the State of Ohio, County of Muskingum, Township of Highland, and being a part of the Northwest Quarter of Section 19, Township 2, Range 5, United States Military Lands, and being part of the lands presently owned by Fracker Farm LLC, as per Official Record 3228, Page 664, (Exhibit B), and being more particularly described as follows:

Beginning for reference and the principal place of beginning, at an iron pin found on the northwest corner of Section 19, Township 2, Range 5, United States Military Lands;

Thence along the section line, and the south line of lands presently owned by Harper D. and Donna J. Ross, Trustees, (OR 3120-580), South 87 degrees 59 minutes 08 seconds East, 393.76 feet to an iron pin found, on the northwest corner of lands presently owned by Clarence S. and Patricia D. Hickenbottom, (OR 2876-386);

Thence along the lines of said Hickenbottom lands the following two courses:

- 1.) South 02 degrees 00 minutes 07 seconds West, 174.41 feet to an iron pin found;
- 2.) South 87 degrees 44 minutes 39 seconds East, 271.31 feet to a point in the centerline of Friendship Drive, (St. Rte. 83, R\W 60'), passing an iron pin found at 240.49 feet;

Thence along the centerline of said drive the following three courses:

- 1.) Along a non-tangent curve to the left with a delta angle of 12 degrees 08 minutes 59 seconds, a radius of 968.40, and arc length of 205.35 feet, and a chord which bears South 17 degrees 37 minutes 30 seconds East, 204.97 feet to a point;
- 2.) Along a non-tangent curve to the right with a delta angle of 3 degrees 46 minutes 46 seconds, a radius of 5351.12 feet, an arc length of 352.99 feet, and a chord which bears South 21 degrees 31 minutes 34 seconds East, 352.92 feet to a point;
- 3.) South 19 degrees 37 minutes 15 seconds East, 90.77 feet to a point;

Thence through the lands presently owned by Fracker Farm LLC, (OR 3228-664) the following three courses:

- 1.) South 68 degrees 58 minutes 46 seconds West, 216.72 feet to an iron pin found, passing an iron pin found at 30.86 feet;
- 2.) South 16 degrees 51 minutes 56 seconds East, 213.09 feet to an iron pin found;
- 3.) South 82 degrees 22 minutes 03 seconds East, 40.23 feet to an iron pin found on the southwest corner of lands presently owned by Michael J. Yarger, (OR 1158-243);

Thence along the south line of said Yarger lands, North 88 degrees 59 minutes 52 seconds East, 201.63 feet to a point in the centerline of said Friendship Drive, passing an iron pin found at 170.33 feet;

Thence along the centerline of said drive, South 19 degrees 08 minutes 49 seconds East, 510.17 feet to a point on the northeast corner of lands presently owned by Fracker Farm LLC, OR 3228-664, (Exhibit A);

Thence along the lines of said Fracker Farm LLC, the following three courses:

- 1.) South 73 degrees 42 minutes 47 seconds West, 445.76 to an iron pin found, passing iron pins found at 29.65 feet and 214.35 feet;
- 2.) South 05 degrees 54 minutes 10 seconds East, 546.90 feet to an iron pin found;
- 3.) South 06 degrees 27 minutes 50 seconds West, 442.71 feet to a point, on the quarter section