## John Scott Rankin

Situated in the State of Ohio, County of Muskingum, Township of Hopewell, Township 18, Range 15, being part of the Northeast Quarter of Section 8, bounded and described as follows:

Being of Parcel No. 25-80-08-04-000. Deed Vol. 1106, Page 306, bounded and described as follows:

Commencing at an iron pin found at the Northeast Corner of the Northeast Ouarter of Section 8; Thence South 88°47'22" West 1331.69 feet to a point in Rankin Lane passing an iron pin found at 1311.69 feet; Thence along Rankin Lane South 22°22'11" East The Place Of Beginning 538.94 feet to an iron pin found at the intersection of the center of Palmer Road; Thence along John Scott Rankin Vol. 1106, Page 306 and in Palmer Road the next 2 courses and distances: North 60°18'23" East 145.61 feet to a point, and North 66°46'40" East 550.03 feet to a point; Thence leaving Palmer Road South 00°39'02" East 1086.93 feet to an iron pin found at the intersection of the center of Asbury Chaple Road passing an iron pins found at 7.02 feet, 482.27 feet and 864.92 feet; Thence along the center of Asbury Chaple Road and Lolita A. Korminar Vol. 1075, Page 75 the next seven courses and distances: North 53°15'45" West 61.22 feet to a point, North 55°58'03" West 69.49 feet to a point, North 48°22'00" West 121.05 feet to a point, North 40°02'01" West 167.01 feet to a point, North 38°59'02" West 253.27 feet to a point, North 38°06'08" West 171.12 feet to a point and North 32°42'00" West 193.99 feet to a rail road spike set in Palmer Road; Thence in Palmer Road North 57°14'55" East 35.63 feet to the intersection of Rankin Lane the place of beginning containing 9.19 acres more or less.

Bearings are based on the North line of the Northeast Quarter of Section 8 bearing South 88°47'22" West.

Above description is based on the survey by R.L. Daniels, Registered Surveyor No. 5410, July 02, 1998 and is intended for legal transfer of property described and does not intend to describe all or any easements of record nor encroachments unless otherwise indicated.

Iron pins set are No. 5 reinf. bars 30 inches long with plastic ID caps.

Ref. Vol. 1106, Page 306

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER BY

7-2-98

OFFICE COPY NOT RECORDABLE

