



**Linn Engineering, Inc.**

*Civil Engineering Consultants*

740-452-7434 • 1-800-991-7086 • FAX 740-452-5198  
534 Market Street • P.O. Box 2086 • Janesville, Ohio 43702-2086

SNR  
N/A

Situated in the State of Ohio, County of Muskingum, Township of Muskingum, bounded and described as follows:

Being part of Section 20, Township 2 North, Range 8 West, and being more particularly described as follows:

Beginning for reference at a stone found at the southwest corner of the Southwest Quarter of Section 20;  
thence along the south line of Section 29 and the south line of lands now owned by B.G. and R.A. Jasper (DR 1147-677) South 87 degrees 34 minutes 20 seconds East 1437.88 feet to an iron pin set and the principal place of beginning;  
thence through said Jaspers' lands North 38 degrees 23 minutes 04 second East 627.55 feet to an iron pin found on the northeast corner of lands now owned by G. and L. Edgell (DR 1143-700);  
thence South 05 degrees 13 minutes 47 seconds East 512.55 feet to an axle found on the north line of lands now owned by J.E. Bunting (DR 757-172),  
thence along said Bunting's north line and the south line of said Section 20 North 87 degrees 34 minutes 20 second West 436.78 feet to the principal place of beginning, containing 2.55 acres, more or less, subject to all legal road right of ways and applicable easements, written or implied.

Bearings are based on the south line of Section 20 as being South 85 degrees 11 minutes 36 seconds East.

This description is written based on a survey completed June 28, 2000 by Jack D. Newcome, Reg. No. 7321.

**OFFICE COPY**  
**NOT RECORDABLE**

06/28/00  
Date

DESCRIPTION APPROVED  
FOR AUDITOR'S TRANSFER  
BY K. Buehly  
6-30-2000

Parcel No.:

Part of: 44-40-02-19-000 (2.55 ac.)

*The State of Ohio, County of Muskingum Township of Muskingum, and being a part of Section 20, T2N, R8W, U.S.M.L.*

- ☒ Iron Pin Set, 5/8" rebar
- ☒ Iron Pin Found
- ☒ Axle Found
- ☒ Stone Found
- ☐ Properly Hoak



Bearings are based on the south line of Section 20 as being S87°34'20"E.

Part of: 44-40-02-18-000 ( $\pm 2.55$  ac.)

6-30-2000

**OFFICE COPY**

**NOT RECORDED**  
Jad. 21, 404, 1000  
Reg. Surveyor No. 7021

Project No.: JASD-058

**Lin Engineering, Inc.**  
Civil Engineering Consultants  
P.O. Box 2038 - Burnsville, Ohio 43702-2038  
740-462-7434