



RICHLAND ENGINEERING LIMITED

2770 Lexington Ave/P.O. Box 3145/Mansfield, Ohio 44904 • 419/864-0074

85010

August 7, 1986

**PROPERTY DESCRIPTION FOR ADDITIONAL ZANESVILLE MUNICIPAL AIRPORT
LAND TO BE ACQUIRED FROM MYRON E. & THELMA L. McCAUL**

The following real estate situated in the County of Muskingum and in the Township of Salt Creek and bounded and described as follows:

Being part of Township 13, Range 12 and being part of the northeast quarter of Section 5 and being more particularly described as follows:

Beginning at the northwest corner of the northeast quarter of Section 5 in said Township and range; thence South 83° 43' East along the north line of Section 5 a distance of 733.05 feet;

thence South 06° 05' West, a distance of 980.35 feet;

thence North 83° 55' West, a distance of 733.05 feet;

thence North 06° 05' East, a distance of 982.91 feet to the point of beginning, the area containing 719,584 square feet (16.519 acres) more or less.

I hereby certify that this description is a true delineation of a survey made for the City of Zanesville by Richland Engineering Limited, Consulting Engineers,

DESCRIPTION APPROVED
for Auditor's transfer
By J. L. Nambel
8-12-86

**OFFICE COPY
NOT RECORDABLE**
David A. Armstrong
David A. Armstrong, Reg. #5788

Date: 8-7-86

DESCRIPTION APPROVED
for 1st floor's transfer.

By J. L. Hambl
8-12-86

ZANESVILLE MUNICIPAL
AIRPORT

NE

SCALE: 1" = 200'

P.O.B.

N 89° 43' W

NORTH

SECTION 5

WEST LINE N.E. 1/4 SECTION

N 89° 43' E

733.05'

719.58' S.E.
16.519 AC.

200.02' N 21° 38' W

701.74' 982.91' N 06° 05' E

980.35' 506° 05' W

MYRON
POWELSON

MYRON E. &
THELMA L.
MC CALL
50.5 AC. O
-16.528 AC. T
=33.972 AC. R

LEGEND

- CURRENT AIRPORT PROPERTY LINE
- PROPOSED AIRPORT PROPERTY LINE
- MONUMENTS FOUND
- MONUMENTS SET

I HEREBY CERTIFY THAT THIS PLAT IS A TRUE DELINEATION OF
A SURVEY MADE FOR THE CITY OF ZANESVILLE BY
RICHLAND ENGINEERING LIMITED, CONSULTING
ENGINEERS

DATE: 8-7-86
DAVID A. ARMSTRONG SURVEYOR NO. 5788

ZANESVILLE MUNICIPAL AIRPORT
ZANESVILLE, OHIO

OFFICE COPY
NOT RECORDED