

Legal Description

Situated in the Township of Perry, County of Muskingum, State of Ohio:

Being part of the southwest quarter of Sec 12, Township 1, Range 6 bounded and described as follows:

Commencing at the southwest corner of Section 12;

Thence North for 1749.39 feet to the center of the National Road, along the west line of said section, said point being the northeast corner of parcel recorded

in Volume 795 Page 299; Thence N $70^{\circ}20'05''$ E along the center of the National Road (State Route 46)

for 496.02 feet to the intersection with Urban Hill Road; Thence S $14^{\circ}02'16''$ E for 66.02 feet to a point in said road; Thence S $7^{\circ}27'49''$ E for 156.59 feet to a point in said road and the point of beginning:

Thence S $82^{\circ}32'11''$ W for 20 feet to an iron pin;

Thence S $32^{\circ}22'28''$ W for 230.30 feet to an iron pin;

Thence S $74^{\circ}23'28''$ W for 47.50 feet to an iron pin;

Thence S $3^{\circ}28'39''$ W for 106.68 feet to an iron pin;

Thence N $71^{\circ}49'18''$ E for 38.70 feet to an iron pin;

Thence S $1^{\circ}02'43''$ W for 141.41 feet to an iron pin;

Thence S $88^{\circ}56'19''$ E for 185.35 feet to a point in Salt Creek, passing through an iron pin at 152.35 feet;

Thence N $12^{\circ}46'00''$ W for 31.33 feet to a point in said creek;

Thence N $37^{\circ}13'00''$ E for 86.61 feet to the center of a bridge;

said point being called for on adjoining deed (Volume 988 Page 602);

Thence N $25^{\circ}27'06''$ W for 39.77 feet to a point in the center of said road at the north end of the bridge;


Thence N $17^{\circ}17'21''$ W for 66.31 feet to a point in said road;

Thence N $7^{\circ}27'51''$ W for 252.51 feet to the point of beginning containing 1.65 Acres

Subject to all legal highways

Surveyed by Loren G. [unclear] #5-5843 March 27, 1981

OFFICE COPY
NOT RECORDABLE



Being part of the S.W.
 Quarter Sec. 12 Twp. 1 Rg 6
 Charles & Isabelle Foraker
 Vol. 443/496 (31 AC)
 Perry Twp.

DEEDS SECTION 12
 for Auditor's transfer

[Signature]

OFFICE COPY
 NOT RECORDABLE
 128/81

5-5843