

Rich Hill Township
S.W. Qtr. Sec. 11
N.W., S.W., & S.E. Qtr.'s Section 14
N.W. & N.E. Qtr.'s Sec. 23
N.W. Qtr. Sec. 24
T-13 N; R-11 W
Congress Lands East
of the Scioto River
Muskingum County, Ohio
SURVEYED FOR: Blessings Acre Farm LLC


REFERENCES
Deeds as shown
Survey on file at Muskingum County Engineer's Office
Basis of Bearing from Grid North: Ohio State Plane Coordinates
System: South Zone NAD 83



- Blank
- 5/8" Metal Found unless noted
- 5/8" Capped Pin Found "Noted"
- Pin Found
- 5/8" Capped Pin Found "Turn End"
- 5/8" Capped Pin Found "Bleeding"
- 5/8" Capped Pin Found "Subsided"
- 5/8" Capped Pin Set "Subsided"
- Pin

CURVE	CHORD	ARC LENGTH	CHORD BEARING	DELTA ANGLE
1	100.00	100.00	0.00° 00' 00"	0.00°
2	100.00	100.00	0.00° 00' 00"	0.00°
3	100.00	100.00	0.00° 00' 00"	0.00°
4	100.00	100.00	0.00° 00' 00"	0.00°
5	100.00	100.00	0.00° 00' 00"	0.00°
6	100.00	100.00	0.00° 00' 00"	0.00°
7	100.00	100.00	0.00° 00' 00"	0.00°
8	100.00	100.00	0.00° 00' 00"	0.00°
9	100.00	100.00	0.00° 00' 00"	0.00°
10	100.00	100.00	0.00° 00' 00"	0.00°
11	100.00	100.00	0.00° 00' 00"	0.00°
12	100.00	100.00	0.00° 00' 00"	0.00°
13	100.00	100.00	0.00° 00' 00"	0.00°
14	100.00	100.00	0.00° 00' 00"	0.00°
15	100.00	100.00	0.00° 00' 00"	0.00°
16	100.00	100.00	0.00° 00' 00"	0.00°
17	100.00	100.00	0.00° 00' 00"	0.00°
18	100.00	100.00	0.00° 00' 00"	0.00°
19	100.00	100.00	0.00° 00' 00"	0.00°
20	100.00	100.00	0.00° 00' 00"	0.00°
21	100.00	100.00	0.00° 00' 00"	0.00°
22	100.00	100.00	0.00° 00' 00"	0.00°
23	100.00	100.00	0.00° 00' 00"	0.00°
24	100.00	100.00	0.00° 00' 00"	0.00°
25	100.00	100.00	0.00° 00' 00"	0.00°
26	100.00	100.00	0.00° 00' 00"	0.00°
27	100.00	100.00	0.00° 00' 00"	0.00°
28	100.00	100.00	0.00° 00' 00"	0.00°
29	100.00	100.00	0.00° 00' 00"	0.00°
30	100.00	100.00	0.00° 00' 00"	0.00°

LINE	BEARING	DISTANCE
1	S 89° 10' 00" E	100.00
2	S 89° 10' 00" E	100.00
3	S 89° 10' 00" E	100.00
4	S 89° 10' 00" E	100.00
5	S 89° 10' 00" E	100.00
6	S 89° 10' 00" E	100.00
7	S 89° 10' 00" E	100.00
8	S 89° 10' 00" E	100.00
9	S 89° 10' 00" E	100.00
10	S 89° 10' 00" E	100.00
11	S 89° 10' 00" E	100.00
12	S 89° 10' 00" E	100.00
13	S 89° 10' 00" E	100.00
14	S 89° 10' 00" E	100.00
15	S 89° 10' 00" E	100.00
16	S 89° 10' 00" E	100.00
17	S 89° 10' 00" E	100.00
18	S 89° 10' 00" E	100.00
19	S 89° 10' 00" E	100.00
20	S 89° 10' 00" E	100.00
21	S 89° 10' 00" E	100.00
22	S 89° 10' 00" E	100.00
23	S 89° 10' 00" E	100.00
24	S 89° 10' 00" E	100.00
25	S 89° 10' 00" E	100.00
26	S 89° 10' 00" E	100.00
27	S 89° 10' 00" E	100.00
28	S 89° 10' 00" E	100.00
29	S 89° 10' 00" E	100.00
30	S 89° 10' 00" E	100.00



**OFFICE COPY
NOT RECORDABLE**

DESCRIPTION
APPROVED
By: *[Signature]* 1/18/2024

Pioneer Surveying & Services, LLC
1614 Township Road 377
Middletown, Ohio 44864
Phone: (330) 211-0400
Email: cs@pioneer-surveying.com



Reduced copy, not to scale, Larger
copy available in the Muskingum
County Engineer's Map Dept.