

State of Ohio, County of Muskingum,
Township of Muskingum,
Being part of Section 4,
Township 2, Range 8,
United States Military Lands

Bearings are based on the Ohio State
Plane Coordinate System, NAD
83(2011), South Zone, Grid North, as
per GPS observations

LINE	BEARING	DISTANCE
L1	S 85°16'33" E	82.22'
L2	S 85°16'33" E	82.23'
L3	S 87°23'10" E	20.13'
L4	S 87°22'58" E	45.00'
L5	S 02°37'05" W	41.22

State of Ohio
OR 1161-149

C/L
Frazeysburg
Road
(St. Rte. 60)

Adam L. and Tracey L.
Herron
OR 2869-273

S 87°59'39" E
131.63'

Farm Supply Center, Inc.
DR 948-26

All of Parcel No.
44-02-04-10-000
±2.19 Ac.
(±0.22 ac. in R/W Co.
Rd. 48) \

All of Parcel No.
44-02-04-11-000
±5.79 Ac.

All of Parcel No.
44-02-04-09-000
±25.36 Ac.

All of Parcel No.
44-02-04-08-000
±4.05 Ac.
5 ac. in R/W Co. Rd. 48)

Shannon Road
(Co. Rd. 48)
R/W 40'

Farm Supply Center, Inc.
DR 948-26

All of Parcel No.
44-02-04-16-000
±22.34 Ac.
(±0.22 ac. in R/W
Co. Rd. 48)

All of Parcel No.
44-02-04-17-000
±66.65 Ac.
(±0.17 ac. in R/W St. Rte. 60)
(±0.77 ac. in R/W Co. Rd. 48)

State of Ohio,
OR 1155-945

Jeffrey C. Jordan
OR 2832-222
±144.43 Acres
(±0.60 Ac. in R/W St. Rte. 60)
(±1.57 Ac. in R/W Co. Rd. 48)

- Iron Pin Set 5/8" Dia. rebar 30" Long
- Iron Pin Found 5/8" Dia.
- ◎ Iron Pipe Found ¾" I.D.
- 田 Stone Found
- ▲ Point
- ⊗ Fence Post Corner
- ✕ Fence Line

D=28°02'54"
R= 1637.02'
A= 801.38'
S 11°24'22" E
793.40'

William A. and Kristen J.
Huston
OR 2442-373

Iron Pin Fd. "Donaker",
and P.O.B., on the SW
Cor. of the SE Qtr. of Sec.
4, T-2 R-8, U.S.M.L.

-www.mceo.org
 -All deed Ref.
 shown on this plat

All of Parcel No.
44-02-04-18-000
±18.05Ac.
(+0.43 ac. in R/W St. Rte. 60)

Section 4
Section 7


William A. and Kristen J.
Huston
OR 2442-373

James R. and Marlene C.
Helt
OR 2881-333

By: Mr. 127125

OFFICE COPY

Jack D. Newcome
Reg. Surveyor No. 7321



Graphic Scale in feet: 1" = 400'

Newcome Surveying Company
6515 Ballard Road
Nashport, Ohio 43830
740-452-5796