

Don Jordan  
3/14/94

Situated in the State of Ohio, County of Muskingum, Township of Union, Township 1, Range 5, part of the Northwest Quarter of Section 13, bounded and described as follows:

Parcel One:

66-50-13-17

Commencing at the Northwest corner of the Northwest Quarter of Section 13; thence on West line of said quarter section South  $0^{\circ} 00' 00''$  West 996.88 feet to an iron pin, the place of beginning; thence North  $84^{\circ} 21' 53''$  East 1354.45 feet to an iron pin; thence South  $3^{\circ} 10' 58''$  East 879.76 feet to an iron pin set; thence South  $86^{\circ} 10' 44''$  East 414.29 feet to an iron pin set; thence South  $0^{\circ} 31' 48''$  West along Geyer 875.49 feet to an iron pin; thence North  $89^{\circ} 45' 00''$  West along P. & M. Hicker 779.09 feet to an iron pin; thence North  $18^{\circ} 06' 34''$  West 1376.54 feet to an iron pin; thence North  $88^{\circ} 34' 03''$  West 595.25 feet to an iron pin on the West line of the Northwest Quarter of Section 13; thence North  $0^{\circ} 00' 00''$  East 321.91 feet to the place of beginning, containing 38.42 acres more or less.

Parcel Two:

66-50-13-17-002 SOS MADSE EYE DA

Commencing at the Northwest corner of the Northwest Quarter of Section 13; thence on the West line of said quarter section South  $0^{\circ} 00' 00''$  West 996.88 feet to an iron pin; thence leaving said quarter section line North  $84^{\circ} 21' 53''$  East 1354.45 feet to an iron pin found, the place of beginning; thence North  $4^{\circ} 03' 06''$  East 43.77 feet to an iron pin; thence South  $85^{\circ} 46' 48''$  East 448.97 feet to an iron pin; thence South  $14^{\circ} 53' 53''$  East 105.44 feet to a point; thence North  $81^{\circ} 27' 12''$  West 182.45 feet to an iron pin, passing an iron pin at 10.00 feet; thence South  $6^{\circ} 56' 58''$  West 323.23 feet to an iron pin; thence North  $89^{\circ} 25' 03''$  East 208.64 feet to an iron pin; thence South  $0^{\circ} 31' 48''$  West 523.14 feet to an iron pin set; thence North  $86^{\circ} 10' 44''$  West 414.29 feet to an iron pin set; thence North  $3^{\circ} 10' 58''$  West 879.76 feet to the place of beginning, containing 7.97 acres more or less.

Bearings are based on the West line of the Northwest Quarter of Section 13 bearing South  $0^{\circ} 00' 00''$  West.

Being Auditor's Parcel Number 66-66-50-13-17.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.


OFFICE COPY  
NOT RECORDABLE  
R. L. Daniels  
Registered Surveyor No. 5410

DESCRIPTION APPROVED  
FOR AUDITORS TRANSFER

BY

3-14-94

MNCor  
 NW Qtr  
 Sec. 13



DESCRIPTION APPROVED  
 FOR AUDITORS TRANSFER  
 BY A. P. Swinchart  
 3-14-94

Rt M. Bricker 560-317

- Iron Pins
- Irons Set No. 5 Reins  
 Bars 30" Lg. Plastic  
 I.D. Caps.

Witness Donald Jordan  
 Plat No. 66-66-50-13-17  
 Daniel's Reg. Surveyor  
 No. 240, 1/14/94  
 Murray County, Union  
 Town of R5, Part of  
 N.W. 1/4, 3-18

OFFICE COPY  
 NOT RECORDED