

SITUATED IN:

State of Ohio, County of Muskingum, Township of Washington, and being part of the Southeast Quarter of Section 9, Township 1, Range 7, United State Military Lands

BASIS OF BEARINGS

Bearings are based on the Ohio State Plane Coordinate System, NAD 83, South Zone, Grid North as per GPS observations.

REFERENCES

Previous survey by C. Harkness

PARCEL NO.

70-15-09-13-000

LEGEND

- △ Railroad Spike Set
- Iron Pin Found
- ⊕ Stone Found
- Axle Found
- Iron Pipe Found
- ▲ Railroad Spike Found
- ⊙ Iron Pin Set, 5/8" rebar 30" Long
- ⊠ Monument Found

Marshall D. and
Charlotte C. Landry
OR 2870-857

Centerline of
Church Hill Road
(Co. Rd. 110)

Centerline of St. Rte. 93



OFFICE COPY

Jack D. Newcome 3-31-23
Jack D. Newcome Date

Reg. Surveyor No. 7321

NOT RECORDABLE

