

JOHN E. MARSHALL  
REGISTERED SURVEYOR  
530 LONGVIEW AVENUE  
ZANESVILLE, OHIO 43701

1052  
4-23-82

84-52-0149  
1382 LEWIS DR

SITUATED IN THE STATE OF OHIO COUNTY OF  
MUSKINGUM AND CITY OF ZANESVILLE.

BEING IN THE THIRD VIEIRD CITY OF ZANESVILLE,  
BOUNDED AND DESCRIBED AS FOLLOWS

COMMENCING AT THE NORTHWEST CORNER OF  
LOT 11 OF MITCHELL'S SUBDIVISION AND RECORDED  
IN PLAT BOOK 1, PAGE 277 OF THE PLAT RECORDS OF  
SAID COUNTY; THENCE NORTH 14 DEGREES 30  
MINUTES EAST ALONG THE EASTERLY RIGHT OF  
WAY LINE OF LEWIS DRIVE [NORTH RIVER RD.]  
A DISTANCE OF 70.00 FEET TO AN IRON PIN AT THE  
TRUE PLACE OF BEGINNING FOR THE PARCEL  
HEREIN INTENDED TO BE DESCRIBED; THENCE  
CONTINUING NORTH 14 DEGREES 30 MINUTES EAST  
ALONG SAID RIGHT OF WAY LINE A DISTANCE OF  
51.98 FEET TO AN IRON PIN; THENCE SOUTH 75  
DEGREES 30 MINUTES EAST ALONG THE SOUTHERL  
LINE OF LANDS HOW CR FORMERLY OWNED BY T.  
SHELTON AND RECORDED IN DEED BOOK 683, PAGE  
108 OF THE DEED RECORDS OF SAID COUNTY A  
DISTANCE OF 148.72 FEET TO AN IRON PIN; THENCE  
SOUTH 14 DEGREES 40 MINUTES WEST ALONG THE  
WESTERLY RIGHT OF WAY LINE OF A 16.5 FOOT ALLEY

DESCRIPTION APPROVED  
for Auditor's transfer.

By \_\_\_\_\_

OFFICE COPY  
NOT RECORDABLE

ECR2

A DISTANCE OF 32.40 FEET TO AN IRON PIN; THENCE  
WORTH 83 DEGREES COMMINUTES WEST ALONG THE  
NORTHERLY LINE OF LANDS NOW OR FORMERLY OWNED  
BY T. ROLL AND RECORDED IN DEED BOOK A77, PAGE  
393 OF THE DEED RECORDS OF SWID COUNTY A  
DISTANCE OF 150.00 FEET TO THE TRUE PLACE OF  
BEGINNING, CONTAINING FOURTEEN [0.14] HUNDERTHS  
OF AN ACRE MORE OR LESS.

THIS DESCRIPTION WAS WRITTEN APRIL 23, 1982 BY  
JOHN R. MARSHALL REGISTERED SURVEYOR NO 5307


DESCRIPTION APPROVED  
for Auditor's transfer

By \_\_\_\_\_

OFFICE COPY  
NOT RECORDABLE

JOHN R. MARSHALL  
REGISTERED SURVEYOR  
530 LONGVIEW AVENUE  
ZANESVILLE, OHIO 43701

84-52



PLAT SHOWING  
0.14 ACRES

BEING IN THE THIRD WARD CITY  
OF ZANESVILLE, MUSKINGUM  
COUNTY, OHIO.

DATE: APRIL 23, 1982

NOT RECORDABLE  
OFFICE COPY  
NOT RECORDABLE  
REGISTERED SURVEYOR 5301