

Harry McCaughey
9/19/94

Situated in the State of Ohio, County of Muskingum, Township of Clay,
Township 14, Range 14, Section 10, bounded and described as follows:

Commencing at a stone found at the Northeast corner of the Southwest Quarter of Section 10; thence South $0^{\circ} 00' 00''$ East along F. Thompson, Vol. 1062, Page 235, 535.86 feet to an iron pin set, the place of beginning; thence continuing along F. Thompson the next two courses and distances, South $0^{\circ} 00' 00''$ East 323.46 feet to an iron pin found and South $89^{\circ} 51' 55''$ East 434.03 feet to an iron pin set; thence along H. Runkle, Vol. 553, Page 943, South $0^{\circ} 00' 00''$ East 417.48 feet to an iron pin set; thence along M. & L. Toth, Vol. 737, Page 52, South $88^{\circ} 52' 28''$ West 434.09 feet to an iron pin set; thence continuing along M. & L. Toth South $0^{\circ} 00' 00''$ East 338.97 feet to an iron pin set; thence North $61^{\circ} 02' 27''$ West along G. & A. Fluharty, Vol. 418, Page 25, 1091.59 feet to the center of Elks Run Road, passing an iron pin set at 1071.59 feet; thence along Kay Smith, Vol. 996, Page 392, in the center of Elks Run Road the next three (3) courses and distances, North $28^{\circ} 44' 01''$ East 34.00 feet to a point, North $24^{\circ} 00' 52''$ East 153.68 feet to a point and North $18^{\circ} 48' 28''$ East 79.83 feet to a point; thence leaving Elks Run Road and along Olena Lockett et al., Vol. 689, Page, 257 and old abandoned road the next four (4) courses and distances, North $29^{\circ} 11' 28''$ East 234.56 feet to a point, North $25^{\circ} 11' 47''$ East 163.81 feet to a point, North $24^{\circ} 26' 47''$ East 177.35 feet to a point and North $21^{\circ} 16' 47''$ East 74.93 feet to an iron pin set; thence along B. Binder, Vol. 1075, Page 204, South $64^{\circ} 33' 41''$ East 626.47 feet to the place of beginning, containing 22.70 acres more or less.

Being all of Auditor's Parcel Numbers 13-13-40-10-15-000
13-13-40-10-16-000.

Bearings are based on the East line of the Southwest Quarter bearing
South $0^{\circ} 00' 00''$ West.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic
I. D. caps.

Reference: Volume 377, Page 389.

Survey & Description by:

R. L. Daniels

Registered Surveyor No. 5410

DESCRIPTION APPROVED
FOR AUDITORS TRANSFER

BY

9-20-94



a-b N 28° 44' 01" E 34.00
 b-c N 24° 00' 52" E 53.68
 c-d N 18° 48' 28" E 79.83
 d-e N 29° 11' 28" E 234.56
 e-f N 25° 11' 47" E 163.81
 f-g N 24° 26' 47" E 177.35
 g-h N 21° 16' 47" E 74.93

● Iron Pins Set No 5 Reinf.
 Bar 30" Lg Plastic ID Cap h
 ○ Iron Pins Found

olena
 Luckett
 689-257

B. Binder
 1075-203

NE Cor
 SW Qtr
 Sec. 10

DESCRIPTION APPROVED
 FOR AUDITORS TRANSFER

BY Ad Smith
 9-20-94

18.54 Ac


22.70 Total

13-13-40-10-15-000

Kay.
 Smith
 996-392

20.00
 ELKS Run

G. Fluharty
 418-25



OFFICE COPY
 NOT RECORDABLE
 By Richard L. Daniels Reg Surveyor
 5410 Muskingum County,
 Clay Township, T14, R14,
 Section 10 9/19/94
 Ref Vol. 377-389

535.86
 5000.00' W

223.46

F. Thompson
 1062-235

S 82° 51' 55" E
 454.03

4.16 Ac

13-13-40-10-16
 -000

S 88° 52' 28" W
 434.09

M.H. Toth
 737-52

5000.00' W
 338.97

5000.00' E
 417.48

H. Runkle 553-943

1" = 200'