

SITUATED IN

The Township of Falls, County of Muskingum, State of Ohio and being a part of Bank Lot 16, T-I-N, R-8-W, USML.

<u>LEGEND</u>

- Iron Pin Set, 5/8" rebar
- Iron Pin Found
- Axle Found

BASIS OF BEARINGS

Bearings based on the South Line of Bank Lot 6, as depicted on a plat of Northview Heights, Plat Book II, Page 36A and the South Line of Bank Lot I4 as described in DR 579-I56.

<u>REFERENCES</u>

DR 490-441
DR 1047-209
DR 992-288
DR 579-156
DR 721-273
DR 1055-89
PB. II, Pg. 36A

PARCEL NO.

Part of: 17-17-04-01-29-000 (± 5.54 ac.)

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

BY 12 97 amble 4-06-92



JOSE NO FOR NO. 7321

<u>4-2-92</u> Date



Linn Engineering, Inc.

614-452-7434

Civil Engineering Consultants
P.O. Box 2671 Zanesville, Ohio 43702-2671