17-39-08-19-005

Part Four:

Commencing at an iron pin found at the Northeast corner of said 2.06 acres; thence South 5° 30' 00" West 259.22 feet to an iron pin set, the place of beginning; thence South 5° 30' 00" West along said 2.06 acres 165.91 feet to an iron pin found at the Southeast corner of said 2.06 acres; thence along the South line of said 2.06 acres North 84° 18' 33" West 20.55 feet to an iron pin set; thence along Part Three the next Two (2) courses and distances, North 9° 34' 49" East 148.14 feet to an iron pin set and North 34° 28' 34" East 20.66 feet to the place of beginning, containing 0.054 acres morre or less.

Bearings are based on the survey of 2.06 acres by L. Peter Dinan, Registered Surveyor No. 5451, January 21, 1993.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.


Survey & Description By:

Registered Surveyor No. 5410

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

4/1/92

1



Part Of Parcel No. 18-17-39-08-19-002 Division Of Survey Made By L. Peter Dinan Reg. Surveyor#5451 Jan 21, 1993' For Robert Beardsley 2.06 Acres

- O Iron Pins Found
- * Iron Pins Set No. 5 Reing. Bars 30" Lg. Plastic I.D. Caps

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

4/1/93

Richard Smitht Clarence Perry By R.L. Daniels Reg. Surveyor No. 5410 3/30/93 Muskingum County, Falls Township, Part Of Quarter Township 2, T.I, R. 7.