LANDMARK SURVEYS

, 1915年**,1916年,1917年**

EARL R. DONAKER, P.S.

35-10-71-16 5NR (614) 623-0993 1-800-842-3264

727 Cambridge Road Coshocton, Ohio 43812

> THOMAS H. JOHNSON, Jr., JO ANN P. ROUSE, BETTY F. LUTZ 30.00 Acres

Being 30.00 acres, more or less, part of parcel 35-10-71-16, in the first quarter of township 2 north, range 9 west, United States Military Lands, in the township of Licking, in the county of Muskingum, in the State of Ohio, and more particularly described as follows:

a stone found at the southwest corner of lot 6, Jackson Beginning at Subdivision of the first quarter of township 2 north, range 9 west;

thence, with the south line of lot 6, S.90°00'00"E. 40.71" to a 5/8" steel pin found, said 5/6" steel pin found being the TRUE POINT OF BEGINNING;

thence, continuing with the south line of lot 6, 5.90°00'00"E. 983.16' to a 5/8" steel pin found,

thence, with the property line of Robert & Kristi Todd, 1055/102, the following 2 courses:

1. thence, S.35°01'24"E. 1252:04' to a 5/8" steel pin found; 2. thence, continuing S.35°01'24"E. 30.00' to a point in the centerline of Shannon Valley Road, CR 56;

thence, through the property of Thomas H. Johnson, Jr., Jo Ann P. Rouse, and Betty F. Lutz, 1039/298, 1039/300, 1039/302, and with the centerline of Shannon Valley Road, CR 56, the following 4 courses:

1. thence, S.48°41'00"W. 189.83' to a point; 2. thence, S.45°05'45"W. 180.27' to a point; 3. thence, S.43°48'39"U. 129.69' to a point; 4. thence, S.46°41'24"W. 116.83' to a point;

thence, with the property line of Benjamin T. & Rebecca Moore, 813/314, and continuing with the centerline of Shannon Valley Road, CR 56, S.47°07'34"W. 197.68' to a point;

thence, with the property line of Terrance Bodson, 1056/227, the following 2 courses:

1. thence, N.35°03'24"W. 25.00' to a 5/8" steel pin found;

2. thence, continuing N.35°01'24"W. 998.21' to a 5/8" steel pin found;

with the property line of Gregory Clapper and Stacie Mahaffey, 1057/411, and continuing N.35°01'24"W. 943.60' to the TRUE POINT OF BEGINNING, containing 30.00 acres, more or less, including public road right-of-way and is subject to all easements, rights-of-way, or restrictions, whether recorded or implied.

Bearings are based on Deed Book 103%, page 32, and are for angular calculations only.

Pertinent documents: tax map: 35-10; deeds: 813/314, 1039/298, 1039/300, 1039/302, 1031/32, 1055/102, 1056/227, 1057/411; surveys by: Wayne A. Knisley, George W. Johnson, Earl R. Conaker.


Prior deed: 1039/298, 1039/300, 1039/302.

Description and plat by Landmark Surveys, Earl R. Donaker, Professional Surveyor, #7342, (from a prior survey of the premises: October, 1991), in the month of June, in the year of our Lord one thousand nine hundred and ninaty-two.

Closure good Acreage good


OFFICE COPY NOT RECORDABLE

Plat matches description



SITUATED IN:

State of Ohio, County of Muskingum, Township of Licking, and being part of the Southeast Quarter of Quarter Township One, Township 2, Range 9, United States Military Lands, and the north line of lands presently owned by Benjamin and Rebecca Moore(DR 813-314), Parcel One.



NOTE: Stone found approximately 4 inches by 12 inches, with the top damaged from farm equipment and leaning toward the north. I straightened the stone to a vertical center to reference my survey. This stone was called for in the original deed of Hilty's land.

REFERENCES

DR 813-314 OR 1650-752 OR 1629-808 OR 1850-378 Wetland Retracement Survey by Steven J. Hyde

Property Line Location for Ben Moore

Surveyor's Report

The four iron pins found as shown on the plat were used to re-establish the survey line of Hilty LLC, as per Donaker's survey. The northern most stone on the southeast corner was used per Donaker's survey information. But the southern most stone was the one clearly marked in the field and witnessed by a plastic electric fence post, as were two of the other pins found set by Donaker. The witness fence post appears to have been set in error by the south stone, rather than the north stone which was used for the survey. Donaker's survey plat does not show two stones found, only one, and indicates the stone found is the adjoiner's southwest corner.

The original deeds for both properties call for a stone on the southwestern corner, and as depicted was found. The west line of the property was called to be "north to the center of the road". Using the deed distance (394.02 ft.), and the centerline of the existing road, I retraced the survey. The survey line of Donaker's survey is not the centerline of the existing road, as called for in the original deed.

A Wetland Retracement Survey was performed by Hyde-Leroy land Surveying Inc. and their plat indicates they used Donaker, survey, but aerial targets found in the field, indicate they used the stone to the south on the east(because it was witnessed), and the iron pin on the west, creating even more of an overlap, the main concern of my client was his pond, and per my survey, it is no longer part of the Hilty property.

BASIS OF BEARINGS

Bearings are based on a previous surveys of adjoining properties by E. R. Donaker as described in OR 1850-378, OR 1650-752, and 1629-808.

> W. N. Bradley DR 896-356

> > V. W. Prior

OR 1603-942

NOTE: The the most northerly found stone is

east side of the stone with old survey ribbon

the top was damaged, I placed a drill hole in

The most southerly found stone is

the top and center to reference my survey.

approximately 4 inches by 10 inches with a

chiseled cross, and a plastic electric fence

post was beside it as a witness.

attached. I believe this to be the corner based

approximately 7 inches square and the top

has been damaged due to farm equipment.

An old iron pin was found right beside the

on parole evidence from Ben Moore. Since

Hilty LLC, OR 1850-378 N 85°57'57"E 1323.79' (Rec. Dist. 1323.30')

5 84°47'40"W 1323.16

Overlap Area = +- 0.57 Acres

Benjamin and Rebecca Moore DR 813-314

D FOR CLOSURE

EXEMPT FROM

PLANNING, COMMISSION

Newcome Surveying Company 6515 Ballard Road Nashport, Ohio 740-452-5796

LEGEND

Railroad Spike Set Iron Pin Found


Stone Found

Arle Found

Iron Pipe Found Railroad Spike Found

Iron Pin Set. 5/8" rebar

Monument Found



position and placed a drill hole in the deed of Moore's land and the original

PARCEL NO.

North line of Parcel No.

35-35-10-71-25-000 South line of Parcel No. 35-35-10-71-16-000

N 00°45'19"E 14.97

JACK D NEWCOME