

Linn Engineering, Inc.

Eivil Engineering Consultants
614-452-7434 • FAX 614-452-5198
534 Market Street • P.O. Box 2671 • Zanesville, Ohio 43702-2671

Situated in the State of Ohio, County of Muskingum, Township of Washington, bounded and described as follows:

Being a part of Quarter Township 3 of Township 1 North, Range 7 West, United States Military Lands, and being the lands of Helen R. Howard as recorded in Muskingum County Deed Record 561-323 and more particularly described as follows:

Beginning at the southwest corner of Lot 10 of a re-survey of the Sam Brown Farm at the instance of Muskingum Mining Co. as designated and delineated on Muskingum County Plat Book 2, Page 10;

thence along the west line of said Lot 10 and the east right-of-wey of "unused" Cushing Avenue North 00 degrees 00 minutes 00 seconds East 347.16 feet to an iron pin set;

thence continuing along said west line of Lot 10 North 25 degrees 35 minutes 00 seconds West 182.82 feet to an iron pin set;

thence North 42 degrees 00 minutes 00 seconds East 93.72 feet to an iron pin set on the south right-of-way of Wallwork Avenue and the north line of said Lot 10;

thence along said south line North 79 degrees 56 minutes 00 seconds East 406.56 feet to an iron pin set on the northeast corner of Lot 11 of said subdivision;

thence along the west line of lands now owned by E. Church (Deed Record 958-141) the following three courses: 1) South 00 degrees 34 minutes 39 seconds West 227.00 feet to an iron pin set; 2) North 80 degrees 00 minutes 38 seconds East 380.35 feet to an iron pin set; 3) South 00 degrees 08 minutes 54 seconds East 498.37 feet to an iron pin found;

thence North 89 degrees 30 minutes 00 seconds West 757.68 feet to the place of beginning, passing iron pipes found at 191.48 feet and 396.09 feet and a stone found off line 2.12 feet at 568.30 feet;

containing 9.66 acre, more or less, subject to all legal road right of ways and applicable easements, written or implied.

Iron pins set are 5/8 inch by 30 inch long rebar with a plastic identification cap.

OFFICE COPY
NOT RECORDABLE

