



SURVEY FOR DUNFALLS ASSOCIATION INC.

12-30-00-00

RESETTING AN IRON PIN AT THE
S.W. COR. OF MAPLE STREET AND IN
THE EAST LINE OF MOUND RD TO
THE POWER ADDITION (PBS-81) TO
THE VILLAGE OF DUNCAN FALLS
OHIO.



REF BEARING.

BEARING BASED ON SURVEY
BY HARKNESS SURVEYING &
MAPPING INC.

LEGEND

OIP = IRON PIN (SET), 5/8" REBAR
WITH ID CAPTAIN'S 60293

● IP = IRON PIN (FOUND)
"ORIGINAL"

⊙ = IRON PIN SET IN
CONCRETE (FOUND)
"ORIGINAL"

NOTE:

DISTANCES & ANGLES TO REESTABLISH
SAID CORNER TAKEN FROM SURVEY
BY HARKNESS SURVEYING & MAPPING
O.R. MAY 2001 No 73-84

SQUARE

RESURVEYED BY
SEPT 6TH 2007

