Situated in the State of Ohio, County of Muskingum, Township of Adams:

Being part of the Southwest Quarter, of Section #21, Township #3, Range #6, of the US Military District, **being part of** the James L & Victoria C Durant property recorded in Official Record Volume 1956, Page 943, of said county's deed records, further being known as Muskingum County **Auditor's Parcel Number 02-90-21-02-000**, *SNR* and more particularly described as follows;

Commencing at an iron pin (found) at the common Southern corner for the Southwest and Southeast Quarters of said Section #21, also being on the common line for Adams and Salem Townships of Muskingum County and for Townships #2 and #3 of said US Military District;

- **TIE-1 THENCE North 01 degrees 58 minutes 30 seconds East 658.59 feet** along said Quarter Section line to an iron pin (found) at a common corner for said Durant property and for the Rich & Leslie Vernon property recorded in Official Record Volume 1581, Page 329;
- **TIE-2 THENCE North 69 degrees 07 minutes 50 seconds West 243.62 feet** into said Southwest Quarter of Section #21 and along said Durant and Vernon properties to an iron pin (found);
- TIE-3 THENCE North 56 degrees 10 minutes 05 seconds West 423.07 feet continuing along said Durant and Vernon properties to an iron pin (found);
- TIE-4 THENCE North 02 degrees 40 minutes 00 seconds West 291.45 feet continuing along said Durant and Vernon properties to an iron pin (found);
- TIE-5 THENCE North 79 degrees 02 minutes 30 seconds West 700.00 feet continuing along said Durant and Vernon properties to an iron pin (found);
- **TIE-6 THENCE North 51 degrees 52 minutes 35 seconds West 423.38 feet** continuing along said Durant and Vernon properties to an unmarked point in the roadbed of Adamsville Otsego Road (State Route #93), passing an iron pin (found) at 380.33 feet;
- **TIE-7 THENCE South 68 degrees 30 minutes 00 seconds West 242.55 feet** along said road and common line for said Durant and Vernon properties to the place of beginning for the property herein intended to be described;
- **#1- THENCE South 10 degrees 51 minutes 40 seconds East 357.24 feet** leaving said road and through said Durant property to an iron pin (set) passing an iron pin (set) at 25.00 feet;
- **#2- THENCE South 47 degrees 21 minutes 00 seconds East 121.29 feet** continuing through said Durant property to an iron pin (set);
- **#3- THENCE South 62 degrees 12 minutes 05 seconds West 300.16 feet** continuing through said Durant property to an iron pin (set);
- **#4- THENCE North 53 degrees 31 minutes 15 seconds West 393.98 feet** continuing through said Durant property to an iron pin (set);
- **#5- THENCE North 28 degrees 21 minutes 50 seconds East 119.42 feet** continuing through said Durant property to an iron pin (set);
- **#6- THENCE North 23 degrees 00 minutes 45 seconds West 80.00 feet** continuing through said Durant property to an unmarked point in said roadbed, passing an iron pin (set) at 50.00 feet, also being the center line of a 40 foot wide (20 foot each side) non-exclusive easement Saved From and Granted to the property herein described;

- **#7- THENCE North 66 degrees 59 minutes 15 seconds East 82.91 feet** along said road and said Durant and Vernon properties to an unmarked point;
- **#8- THENCE North 68 degrees 29 minutes 55 seconds East 348.26 feet** continuing along said road and said Durant and Vernon properties to the place of beginning, **containing 4.35 acres**, of which 0.30 acres are within the right of way for State Route #93.

SAVING, EXCEPTING AND GRANTING A NON-EXCLUSIVE EASEMENT

Saving a 20 foot wide easement 80 feet along course #6 of the above described 4.35 acre parcel. Granting a 20 foot wide easement along the West side of course #6 of the above described 4.35 acre parcel extending from the centerline of State Route #93 to course #5 of the above described 4.35 acre parcel, as shown on the survey plat.

The bearings within this description are based on State Plane Coordinate Grid (Ohio South 1983) derived from GPS Observations. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).


This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on November 3, 2005, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.


RECORDABLE #6885



FOR CLOSURE ilis boos

EXEMPT FROM PLANNING COMMISSION





DESCRIPTION OF SURVEY FOR COUNTRYTYME

Situated in the State of Ohio, County of Muskingum, Township of Adams:

Being part of the Southwest Quarter, of Section #21, Township #3, Range #6, of the US Military District, **being part of** the James L & Victoria C Durant property recorded in Official Record Volume 1956, Page 943, of said county's deed records, further being known as Muskingum County **Auditor's Parcel Number 02-90-21-02-000**, 5/V/C and more particularly described as follows;

Commencing at an iron pin (found) at the common Southern corner for the Southwest and Southeast Quarters of said Section #21, also being on the common line for Adams and Salem Townships of Muskingum County and for Townships #2 and #3 of said US Military District;

- TIE-1 THENCE North 01 degrees 58 minutes 30 seconds East 658.59 feet along said Quarter Section line to an iron pin (found) at a common corner for said Durant property and for the Rich & Leslie Vernon property recorded in Official Record Volume 1581, Page 329;
- TIE-2 THENCE North 69 degrees 07 minutes 50 seconds West 243.62 feet into said Southwest Quarter of Section #21 and along said Durant and Vernon properties to an iron pin (found);
- TIE-3 THENCE North 56 degrees 10 minutes 05 seconds West 423.07 feet continuing along said Durant and Vernon properties to an iron pin (found);
- TIE-4 THENCE North 02 degrees 40 minutes 00 seconds West 291.45 feet continuing along said Durant and Vernon properties to an iron pin (found);
- TIE-5 THENCE North 79 degrees 02 minutes 30 seconds West 700.00 feet continuing along said Durant and Vernon properties to an iron pin (found);
- TIE-6 THENCE North 51 degrees 52 minutes 35 seconds West 423.38 feet continuing along said Durant and Vernon properties to an unmarked point in the roadbed of Adamsville Otsego Road (State Route #93), passing an iron pin (found) at 380.33 feet;
- TIE-7 THENCE South 68 degrees 30 minutes 00 seconds West 242.55 feet along said road and common line for said Durant and Vernon properties to the place of beginning for the property herein intended to be described;
- **#1- THENCE South 10 degrees 51 minutes 40 seconds East 357.24 feet** leaving said road and through said Durant property to an iron pin (set) passing an iron pin (set) at 25.00 feet;
- **#2- THENCE South 47 degrees 21 minutes 00 seconds East 121.29 feet** continuing through said Durant property to an iron pin (set);
- **#3- THENCE South 62 degrees 12 minutes 05 seconds West 300.16 feet** continuing through said Durant property to an iron pin (set);
- **#4- THENCE North 53 degrees 31 minutes 15 seconds West 393.98 feet** continuing through said Durant property to an iron pin (set);
- **#5-** THENCE North 21 degrees 47 minutes 20 seconds West 154.21 feet continuing through said Durant property to an unmarked point in said roadbed, passing an iron pin (set) at 118.80 feet;
- #6- THENCE North 64 degrees 51 minutes 30 seconds East 9.73 feet along said road and common line for said Durant and Vernon properties to an unmarked point;

- **#7- THENCE North 66 degrees 59 minutes 15 seconds East 163.18 feet** continuing along said road and said Durant and Vernon properties to an unmarked point;
- **#8- THENCE North 68 degrees 29 minutes 55 seconds East 348.26 feet** continuing along said road and said Durant and Vernon properties to the place of beginning, **containing 4.60 acres**, of which 0.36 acres are within the right of way for State Route **#**93.

The bearings within this description are based on State Plane Coordinate Grid (Ohio South 1983) derived from GPS Observations. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on August 10, 2005, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.

OFFICE COPYLINS NOT RECORD #6885 NOT RECORD #6885



CVED FOR CLOSURE 8.412005