JOB #284

Situated in the State of Ohio. County of Muskingum, Township of Falls, Quarter Township #2, Township #1, Range #8, of the US Military District:

Being all of the remaining portion of prior deed reference Volume 985 Page 57, also being all of Muskingum County Auditor's Parcel Number 17-17-12-02-49-000, and more particularly described as follows;

Commencing at the Northwest corner of Lot #12 of Dillon Acres Subdivision as recorded in Plat Book 8. Page 22 of said County's plat records: thence as described in said prior deed reference Volume 985, Page 57 N 07 20 46 E 50.00 feet to the center of an abandoned Railroad right-of-way of the Southern Dhio Public Service Company, also being the center line of Township Road #668 (Harmony Lane): thence along the center line of said road and railroad N 82 39 14 W 209.56 feet to the Southwest corner of the property described in deed reference Volume 997, Page 179; thence along the West lines of said Volume 997, Page 179 and the property described in deed reference Volume 1007, Page 130 `N 30 44 39 E 363.19 feet to an iron pin (found) at the Northwest corner of said Volume 1007, Page 130 also being the place of beginning for the property herein intended to be described; thence along the West line of the prior deed reference N 30 44 39 E 304.49 feet to an iron pipe (found); thence along the North line of said prior deed reference N 87 26 43 E 1156.98 feet to an iron pin (found) at the center of a 50 foot easement as described in deed reference Volume 1007, Page 147; thence continuing along said North line NS 87 26 43 E 251.99 feet to a metal post (found); thence along the East line of said prior deed reference S 31 57 17 W 94.69 feet to an iron pin (set) in the center of Township Road #668 (Dillon Acres Drive); thence along the center of said road the following four courses-

- #1- N 73 22 59 W 139.00 feet to an iron pin (set);
- #2- N 83 57 23 W 64.22 feet to an iron pin (found) at the center of previously mentioned 50 foot easement;
- along a curve to the left having, a radius of 144.72 feet, an Arc Length of 178.05 feet, and a Chord Bearing S 51 50 05 W 167.03 feet to an iron pin (set), Curve is not tangent;
- #4- S 21 28 00 W 327.67 feet to the Northeast corner of property described in said Volume 1007, Page 130; thence along the North line of said Volume 1007, Page 130 N 83 42 14 W 1071.27 feet to the place of beginning, passing an iron pin (found) at 30.80 feet containing 8.933 acres.

The bearings within this description are based on a Solar Observation (Local Hour Angle Method), completed on the property. Iron pins (set) are 5/8" rebar with aluminum identification caps (C R Harkness R S 6885).


This description was written by Charles R. Harkness Registered Surveyor #6885 from an actual survey completed on February 6, 1989, and is intended to be used for the legal transfer of the property described, and does not intend to show all or an pasement or encroachments unless otherwise indicated.

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

FOR AUDITOR'S TRANSFER

BY Mande

Charles R. Harkness RS 6885



This survey plat was prepared by Charles R. Harkness Registered Surveyor #6885 from an actual survey completed February 6, 1989, and is intended to be used for the legal OFFICE CORD show all or any easements of record, nor encroachments unless otherwise indicated.

Charles R. Harkness RS #6885