17-27-01-30 17-27-01-30-001 1270 RICHEY PD 1230 MITCHEY LD

Michael & Deborah Creeks 2/2/94

Situated in the State of Ohio, County of Muskingum, Township of Falls, part of the First Quarter of Township 1, Range 8, bounded and described as follows:

Parcel One:

Beginning at an axle found at the Northwest corner of Lot 11 of Meadowbrook Subdivision, Recorded in Plat Book 8, Page 47; thence along the West line of said subdivision South 01° 57' 34" East 146.60 feet to an iron pin set; thence leaving subdivision North 85° 26' 25" West 426.99 feet to the center of Richey Road, passing an iron pin set at 405.99 feet; thence along center of Richey Road North 03° 45' 00" East 139.85 feet to a point; thence leaving Richey Road South 86° 15' 00" East 412.37 feet to the place of beginning, passing an axle found at 15.00 feet, containing 1.376 acres more or less.

Parcel Two:

Commencing at an axle found at the Northwest corner of Lot 11 of Meadowbrook Subdivision, Recorded in Plat Book 8, Page 47; thence South 57' 34" East 146.60 feet to an iron pin set, the place of beginning; thence South 1 57' 34" East 32.55 feet to an iron pin found; thence South 25° 55' 46" West 103.30 feet to an iron pin found; thence North 82° 34" 23" West 392.00 feet to the center of Richey Road, passing an iron pin set at 381.33 feet; thence North 03° 45' 00" East along center of Richey Road 108.94 feet to a point; thence South 85° 26' 25" East 426.99 feet to the place of beginning, passing an iron pin set at 21.00 feet, containing 1.137 acres more or less.

Being Auditor's Parcel Numbers $\frac{17-27-01-29-000}{01-30-000}$ and 17-27-01-30-000.

Bearings are based on Meadowbrook Subdivision.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.

Deed Reference: Volume 1060, Page 452.

Survey & Description By:

DESCRIPTION APPROVED

FOR AUDITORS TRANSFER

7-2-94

R. L. Daniels Registered 5410

