DESCRIPTION OF SURVEY FOR ROBERT GRUBB AND LEOMA QUIDAL CORY ABLE.

Situated in the State of Ohio, County of Muskingum, Township of Raise RECOXY ABLE.

Being part of the Third Quarter Township, of Township #1 Range #9 - Col. District, being part of the Leoma Quinn property as described, in the Second Parcel of deed reference Deed Book Volume 573, Page 860, known as Muskingum County Auditor's Parcel Number 17-92-01-74-000 also a part of the Leoma Quinn property as described in Exhibit "A" of deed reference Deed Book Volume 964, Page 120, being Lot #5 of Hills and Dales Estates as recorded in Plat Book 7, Page 5A of said county's deed records, known as a part of Muskingum County Auditor's Parcel Number 17-92-01-75-000, and more particularly described as follows;

Commencing at an iron pin (found) at the common Eastern corner of Lots #4 & #5 of said Hills and Dales Estate; thence S 69 05 00 W 301.67 feet along the North line of said Lot #5 to an iron pin (set by previous survey) at the Southeast corner of said Quinn property as described in the Second Parcel of deed reference Deed Book Volume 573, Page 860, also being the Southwest corner of the G Alfman property as described in deed reference Deed Book Volume 1025, Page 411; thence N 01 34 30 E 65.79 feet along the common line for said Quinn and Alfman properties, crossing Timber Run Creek, to the low water mark of Timber Run, being the place of beginning for the property herein intended to be described, passing an iron pin (found by previous survey) at 8.62 feet;

- thence S 70 12 20 W 9.32 feet through said Quinn property and along said low water #1-
- #2thence S 81 58 50 W 22.50 feet continuing along said low water mark;
- #3thence S 53 25 00 W 30.48 feet continuing along said low water mark;
- #4thence N 31 54 20 W 4.00 feet to an iron pin (set) on the North bank of Timber Run;
- #5thence S 58 05 40 W 18.05 feet to an iron pin (set) on the North side of a concrete dam crossing Timber Run;
- #6thence. N 30 26 20 W 9.26 feet to an iron pin (set) on the North side of said dam;
- #7thence S 62 05 50 W 2.96 feet to an iron pin (set) on the North side of said dam;
- #8thence S 29 34 20 E 9 61 feet to an iron pin (set) on the North side of said dam;
- #9thence S 49 31 30 W 20.21 feet to the low water mark of Timber Run, passing an iron pin (set) on the North side of said dam at 16.21 feet;
- #10thence N 61 17 10 W 5.16 feet continuing along said low water mark;
- #11thence S 49 50 20 W 7.03 feet continuing along said low water mark;
- #12thence S 40 04 10 W 43.52 feet continuing along said low water mark;
- #13thence S 16 09 20 W 39.18 feet continuing along said low water mark to a point on the South line of said Second Parcel of deed reference Deed Book Volume 573, Page 860, also being the North line of said Lot #5;
- #14thence S 13 49 40 W 60.09 feet through said Lot #5 and continuing along said low water mark:
- #15thence S 22 59 40 W 54.61 feet continuing along said low water mark;

- #16- thence S 47 35 50 W 43.56 feet continuing along said low water mark;
- #17- thence N 07 52 50 W 107.45 feet leaving said low water mark to an iron pin (found) on the North line of said Lot #5 and the Southwest corner of said Second Parcel of deed reference Deed Book Volume 573, Page 860, also being the Southeast corner of the P Debolt property as described in deed reference Deed Book Volume 1060, Page 439, passing an iron pin (set) at 13.76 feet;
- #18- thence N 07 52 50 W 75.73 feet along the West line of said Second Parcel and East line of said Debolt property to an iron pipe (found disturbed) at the Southwest corner of the R Grubb property as described in deed reference Volume 1043, Page 495 passing an iron pipe (found) at 1.24 feet;
- #19- thence N 65 33 30 E 256.55 feet along the common line for said Grubb property and said Second Parcel to an axle (found) at the Southeast corner of said Grubb property and Northeast corner of said Second Parcel, also being on the West line of said G Alfman property;
- #20- thence S 01 34 30 W 31.14 feet along the common line for said Alfman and Quinn properties to the place of beginning containing 0.14 acres from said Lot #5 and 0.28 acres from said Second Parcel for a total of 0.42 acres.

The bearings within the description are based on a Solar Observation (Local Hour Angle Method) completed as part of the survey for the Gerald Alfman property as described in deed reference Volume 1025, Page 411. Bearings are shown in a format of Degrees, Minutes, and Seconds. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on February 29, 1996, in accordance with Chapter 4763-37 of the Administrative Code, and is intended to be used for the legal transfer of the people by described and does not intend to describe all or any easements of a tool, nor accordance unless otherwise indicated.

DESCRIPTION APPROVED FOR AUDITORS TRANSFER

OF SIA

6-5-96

Charles R. Harkness RS #6885

Situated in the State of Ohia, County of Muskingum, Township of Falls: The bearings on this plat are based on State LEGEND Plane Coordinate Grid as derived from a Being part of the Third Quarter Township, of Township #1, Range #8, of the US ☐ STONE (FOUND) WITH X = ☒ Solar Observation (Local Hour Angle Method). Military District, being part of Leoma Quinn property as described in the Second Completed as part of the survey for the Gerald Porcel of deed reference Deed Book Volume 573, Page 860, known as Muskingum CONCRETE MONUMENT (FOUND) Alfman property os described in deed County Auditor's Parcel Number 17-92-01-74-000 also being part of the AXLE (FOUND) reference Volume 1025, Page 411. Leoma Quinn property as described in Exhibit "A" of deed reference Deed Book Volume 964, Page 120, being part of Lot #5 of Hills & Dales Estates as recorded IRON PIPE (FOUND) in Plat Book 7. Page 5A of said county's plat records, known as a part of IRON PIN (FOUND) Muskingum County Auditor's Parcel Number 17-92-01-75-000. R. Grubb RAILROAD SPIKE (FOUND) Vol. 1043, Page 495 REFERENCES NOT SHOWN OR PK NAIL (FOUND) LISTED: , Debolt 1060, Page A plot of Hills & Dales Estates Δ POINT as delineated in Plat Book 7. -Disturbed N 65°33'30"E 256.55' Page 5A. IRON PIN (SET BY PREVIOUS SURVEY) A Plat of Westwood Hills Subdivision as delineated in Plat IRON PIN (SET) 5/8" REBAR S 01°34'30"W WITH IDENTIFICATION CAP (C.R. HARKNESS PLS 6885). Book 13, Page 19 & 19A. Total = 0.42 Ac.31.14' Previous surveys completed by IRON PIN (FOUND BY PREVIOUS SURVEY) C.R. Horkness PLS #6885, os Par #17-92-01-74-000 Timber Dam follows: 70°S A 4.26 & 0.46 acre tracts. = 0.28 Ac. 16.21 on7-25-95; 0.969 acre tract. on 9-1-89: 1.00 acre tract & Passing Lot #4 of Hills & Dales Estates. 1.24' on 7-25-89. Passina Muskingum County Tax Maps of 440 North Line 8.62 SE Cor the area. North Line Lot #5 Lot #5 Lot #4 A USGS 7 1/2 Min Topo Quad #17-92-01-85-\$ 69°05'00"\ 301.67' Map (Zanesville West). NE Cor Lot #5 Hills & Dales Esates CALL DATA TABLE: **BEARING** COURSE DISTANCE 50 50 150 100 S 70°12'20"W 9.32' S 81°58'50"W 22.50' Passina S 53°25'00"W 30.48 GRAPHIC SCALE - FEET L. Quinn N 31°54'20"W 4.00' SURVEY FOR: Exhibit "A" Vol. 964, Robert Grubb & Leoma Quinn S 58°05'40"W 18.05' Page 120 9.26' (N 30°26'20"W Around S 62°05'50"W 2.96' Zanesville, Ohio 43701 Dam Site S 29°34'20"E 9.61'(This plat was prepared by Co. Rt. Harkness Surveying & Mapping Inc. in accardance with that 4 33—37 of the Administrative Code, from an actual surrow and is prended to be used for the legal transfer of the property shown and coes not intend to show all or any easements of SECTION: Gir Twp #3 TOWNSHIP:#I RANGE:#B S 49°31'30"W 20.21' TWP: Falls COUNTY: Muskingum STATE OF OHIO Survey Date: 2-29-96 Drw date 3-1-96 By: SBT N 61°17'10"W 5.16' C. R. HARKNESS SURVEYING & MAPPING INC. S 49°50'20"W 7.03' S 40°04'10"W 43.52' 768 DRYDEN ROAD record, nor en to coments unless otherwise indicated. S 16°09'20"W 39.18' Zanesville, Ohio 43701 Phone (614) 454-6367 S 13°49'40"W 60.091 Job Number: Drowing/Sheet No. 15 S 22°59'40"W 54.61' #577 Plat #03 Charles R. Harkness ₱L\$ #6885 43.56' S 47°35'50"W