Situated in the County of Muskingum, Township of Falls, Quarter Township 2, Township 1, Range 7, Lot 6 of Underwoods Subdivision as recorded in Plat Book "A-O", Page 54 and being further described as follows;

Commencing at the southwest corner of the said Lot 6 of Underwoods Subdivision, thence South 840 12' East, 2545.59 feet along the south line of the said Lot 6 to a point on the east line of Riverside Airport Drive (Twp. Rd. 659), thence North  $29^{\circ}$  20' East, 63.91 feet along the east line of the said Twp. Rd. 659, thence North  $37^{\circ}$  18' 55" East, 180.70 feet along the east line of said Twp. Rd. 659 to a concrete monument at the point of curve of the said east line of Twp. Rd 659 (curve to left, radius 2291.65 feet, deflection 200 39' 46", long chord 821.98 feet), thence North 36<sup>0</sup> 29' 27" East, 66.32 feet with a chord of said curve to an existing railroad spike at the northwest corner of R.L. Mast (Deed Book 1081, Page 046) being also the point of beginning of the parcel herein being described, thence, with a chord of the said curve North 340 26' 41" East, 97.33 feet (arc distance 97.34 feet) to an iron pin, set (5/8" X 30" re-bar with ID Cap) on the east line of Twp. Rd 659, (Note: there is an existing iron pin North 230 52' East 1.78 feet from iron pin set),

thence, South 56° 46' 28" East, 155.00 feet along the southerly line of N. Neminich (Deed Book 680, Page 150) to a point at the low water line of the Muskingum River, passing an iron pin, set (5/8" X 30" re-bar with ID Cap) at 110.00 feet (Note: there is an existing iron pin South 75° 30' East, 10.14 feet from iron pin set), thence, South 25° 18' 38" West, 92.80 feet along the said low

water line,

thence, North 58° 25' 28" West, 156.70 feet along the north line of R.L. Mast (Deed Book 1081, Page 046) to the point of beginning, passing an existing iron pin at 38.00 feet,

containing 0.339 acres more or less.

being all of the remainder of Parcel Number 17-17-41-02-11



Survey and Description by William H. Derwacter Registered Surveyor #5437 July 22, 1993

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER BY 7-28-93

