

Situated in the State of Ohio, County of Muskingum, Township of Licking, Quarter Township Four, Township 2, Range 9 and being further described as follows;

Commencing at the southeast corner of Dillon Hills Subdivision as recorded in Flat Book 10, Page 33, thence, South 14° 14' 45" East, 14.00 feet to a point, thence, South 84° 02' 25" East, 521.00 feet along a north line of S. Embrey as recorded in Deed Book 886, Page 337, and Deed Book 1009, Page 569 to an existing iron pin, thence South 20° 25' 25" East, 338.22 feet along an east line of said S. Embrey and M. and J. Vanelli (Deed Book 1006, Page 499) to an iron pin-set (5/8" X 30" re-bar with ID Cap) at the point of beginning of the parcel herein being described,

thence, North 66° 46' 26" East, 216.00 feet along a south line of H. and J. Huey (Deed Book 768, Page 043) to a point at an iron pin-set (5/8" X 30" re-bar with ID Cap),

East thence, South 20° 25' 22" ~~West~~, 499.91 feet across D. and N. Goodyear (Deed Book 549, Page 575) to a point on a north line of W. and B. Rambo (Deed Book 767, Page 367), said point being 28.33 feet left of centerline Station 91 + 38.27 of Township Road 47 (Clay Littick Drive) as surveyed in 1967, passing an iron pin-set (5/8" X 30" re-bar with ID Cap) at 440.94 feet,

thence, South 66° 45' 02" West, 216.00 feet along a north line of said W. and B. Rambo to an existing iron pin at the southwest corner of D. and N. Goodyear (Deed Book 549, Page 575) said point being 7.06 feet right of centerline Station 93 + 51.35 of said Township Road 47,

thence, North 20° 25' 22" West, 500.00 feet along Alique Inc. (Deed Book 919, Page 273) and M. and J. Vanelli (Deed Book 1006, Page 499) to the point of beginning, passing an iron pin-set (5/8" X 30" re-bar with ID Cap) at 25.00 feet, also passing an existing iron pipe at 258.98 feet,


containing 2.476 acres more or less.

Subject to easement of Township Road 47--Clay Littick Drive--easement contains 0.29 acres.



Survey and Description by
OFFICE COPY
NOT RECORDABLE
 William H. Derwacter
 Registered Surveyor No. 5437
 August 3, 1993

DESCRIPTION APPROVED
 FOR AUDITOR'S TRANSFER
 BY *A. L. Smith*
 8-6-93



Southeast Corner
 Dillon Hills Subd.
 Plat Book 10, Page 33
 S 14° 46' 45" E
 14.00'

- Iron Pipe Found
- Iron Pin Found
- Iron Pin Set
- 5/8" x 30" re-bar with identification cap.

S 84° 02' 25" E 521.00'
 886-337

S. Embrey
 1009-569

Basic of Bearing
 TR#47 S 57° 19' 30" W

H & J Huey
 768-043

M. & J. Vanelli
 1006-499

N 66° 46' 26" E
 216.00'

D & N Goodyear
 549-575

DESCRIPTION APPROVED
 FOR AUDITOR'S TRANSFER

BY A.L. Dill
 8-6-93

Passing IP
 at 258.98

Aliquid Inc
 919-273

N 20° 25' 22" W
 500.00'

Total 2.476 Ac.
 In R/W 0.29 Ac.
 Part 35-35-52-04-04

499.91'
 S 20° 25' 22" E

Ex. IP 20' Rt.
 Sta. 94 + 82.31

Passing
 IP at 2500

R/W
 92
 216.00'

Passing IP
 at 440.94'

TR#47
 Clay Littick Dr.

S 66° 45' 02" W

TR#47
 Clay Littick Dr.

W & B Rambo
 767-367

SITUATED IN
 State of Ohio
 County of Muskingum
 Township of Hicking
 Quarter Trp 4
 W & B Rambo



OFFICE COPY
 NOT RECORDABLE
 William H. Denwacker
 Registered Surveyor #5437
 August 6, 1993