DESCRIPTION OF SURVEY FOR RONALD K. MARKEY

JOB#904

Situated in the State of Ohio, County of Muskingum, Township of Salem:

Being part of the Northwest Quarter, of Section #22, Township #2, Range #6, of the US Military District, being all the remaining portion of the Ronald K. Markey. property described in the First Parcel of deed reference Deed Book Volume 558, Page 859 of said county's deed records, known as Muskingum County Auditor's Parcel Number 56-80-22-08-000, and more particularly described as follows:

Beginning at a stone (found) at the center of said Section #22;

- #1thence N 88 03 30 W 866.83 feet along the common line for the Northwest and Southwest Quarters of said Section #22 to the center of Township Road #82 (Murphy Hill Road), passing an iron pin (set) at 841.31 feet;
- #2thence along a curve to the right having a chord bearing N 10 53 30 W 175.10 feet, a radius of 299.12 feet, and arc length of 177.70 feet, into the Northwest Quarter along the center line of said road and common line for said Markey property and the D Weaver property recorded in deed reference Deed Book Volume 1097, Page 141 to a point referenced by an iron pin (set). S 88 13 50 E 18.99 feet;
- #3thence N 02 39 20 E 388.03 feet continuing along the center line of said road and common line for said Markey and Weaver properties to a point referenced. by an iron pin (set) N 89 08 40 E 16.15 feet;
- #4thence N 03 11 20 E 377.71 feet continuing along the center line of seid road and common line for said Markey and Weaver properties to a point referenced. by an iron pin (set) S 85 49 50 E 15.01 feet;
- thence N 01 41 10 E 223.65 feet continuing along the center line of said road #5and common line for said Markey and Weaver properties to a point referenced. by an iron pin (set) S 89 26 30 E 14.70 feet;
- thence N 03 06 30 E 284.53 feet continuing along the center line of said road #6and common line for said Markey and Weaver properties to a point referenced. by an iron pin (set) N 89 51 10 E 14.02 feet;
- thence N 01 47 50 E 429.85 feet continuing along the center line of said road #7and common line for said Markey and Weaver properties to a point referenced by an iron pin (set) S 82 30 00 E 14.03 feet;
- #8thence N 01 49 50 E 312.65 feet continuing along the center line of said road and common line for said Markey and Weaver properties to the Southwest corner of the I Nicholas property recorded in deed reference Deed Book 1039, Page 572:
- #9thence S 65 58 20 E 451.03 feet leaving said road and along the South line of said Nicholas property to an iron pin (found) at the Southeast comer of said Nicholas property, also being the Southwest corner of the B Penn property recorded in deed reference Deed Book Volume 1080, Page 1113, passing an iron pin (found) at 21.04 feet;
- thence S 86 17 00 E 450,50 feet along the South line of said Penn property to the East line of said Northwest Quarter, passing an iron pipe (found) at 446.26.
- #11- thence S 02 14 45 W 2156.63 feet along the common line for the Northwest and Northeast Quarters of said Section #22 to the place of beginning, containing 44,85 acres.

The bearings within the description are based on State Plane Coordinate Grid derived from a Solar Observation (Local Hour Angle Method). Bearings are shown in a format of Degrees, Minutes, and Seconds. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885),

This description was written by Charles R. Harkness Professional Land Surveyor. #6885 from an actual survey completed on October 24, 1998, in accordance with Chapter 4733-37 of the Administrative Code. and is intended to be used for the legal transfer of the all or able unless other the indice.

Of HBE CODD

-das R. Harknight & #6885 property described and does not intend to describe DESCRIPTION AT EX all or an essements of record, nor encroachments FOR AUDITOR'S THANSFER

