

62-62-10-26 PS

Owen Van Horn
12/28/88

4

Situated in the State of Ohio, County of Muskingum, Township of Springfield, T 16, R 14, part of the Southeast Quarter of Section 3, bounded and described as follows:

Beginning at an iron pin found at the Northwest corner of the Southeast Quarter of Section 3; thence on North line of said section South 83° 29' 33" East 297.66 feet to an iron pin set; thence leaving section line South 5° 59' 55" West 1561.80 feet to the center of Ridge Road passing an iron pin set at 1541.80 feet; thence along the center of Ridge Road the following three courses and distances-North 40° 55' 40" West 90.41 feet, North 54° 01' 23" West 112.18 feet and North 66° 26' 53" West 55.13 feet; thence leaving Ridge Road North 6° 01' 47" East 525.00 feet to an iron pin found passing an iron pin found at 30.16 feet; thence North 75° 49' 32" West 32.98 feet to an iron pin found on West line of the Southeast Quarter of Section 3; thence along the West line of Section 3 North 5° 59' 49" East 893.22 feet to the place of beginning, containing 9.03 acres more or less.

Bearings are based on the West line of the Southeast Quarter of Section 3 bearing North 5° 59' 49" East.

Iron Pin Set
Iron Pin Found

Being all of Auditor's Parcel Number 62-62-10-01-26-000.

Subscribed and Description By:

R. L. Daniels
Registered Surveyor No. 5410

OFFICE COPY
NOT RECORDABLE

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER


Part of Owen Van Horn
Property Parcel No.
62-62-10-26-000

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY J. L. Daniels
12/28/88

R. L. DANIELS & ASSOC.
51 W. 12th St.
Muskingum County, Ohio 44660
PH. 191-4211 FAX 191-4210

58°29'53"E
297.66
NW Cor
SE Q6
Sec. 3



1"=200'

9.03Ac

N75°49'32"W
82.98

Iron Pins Set
Iron Pins Found

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY J. L. Gamble
12-30-88

N66°26'53"W
55.13
N54°01'28"W 112.18
N40°55'40"W 90.41

Plat of Owen Yorkhorn
Property Parcel No.
62-62-10-01-26-000
Moskington County,
Springfield Township,
T16, R14, Part of SE
Quarter Section 3.
12/28/88 By R L Daniels
Reg. Surveyor No. 5410

R L DANIELS & ASSOC
61 Rainer Rd.
Roseville, Ohio 43777
Ph. (614) 697-7480

OFFICE COPY
NOT RECORDABLE