

Bearings are based on the Ohio State Plane Coordinate System, NAD 83, South Zone, Grid North, as per GPS observations.


OR 1142-165
DR 203-490
DR 160-83
DR 161-461
DR 148-598
DR 158-357
1911
Cemetery
Survey Plat

State of Ohio, County of Muskingum,
Township of Union, and being part of
Section 2, Township 1, Range 5,
United States Military Lands.

- Railroad Spike Set
- Iron Pin Found
- Stone Found
- Axle Found
- Iron Pipe Found
- Railroad Spike Found
- Iron Pin Set, 5/8" rebar
- Monument Found
- Deed Line
- Parcel Line



All of: 66-20-02-27-001 +- 1.31 Acres
All of: 66-20-02-28-001 +- 0.68 Acres
All of: 66-24-01-01-000 +- 4.07 Acres
(+- 0.36 Acres in R\W of St. Rte 83)



OFFICE COPY
NOT RECORDABLE
Jack D. Newcomb 8-11-16

Jack D. Newcome Date _____
Reg. Surveyor No. 7321

DESCRIPTION
APPROVED
By: [Signature] 8/12/2016

**New Concord
Cemetery
Association
+- 6.06 Acres**

Mark F. and
Teresa A. McCabe
OR 1145-821

Justin M.
Sawyer
OR 2488-210

Justin Michael Sawyer
OR 2251-190

DR 209-480

66-24-01-01-000

Justin Michael Sawyer
OR 2251-190

Newcome Surveying Company
6515 Ballard Road
Nashport, Ohio
740-452-5796