

Southeast Corner
of Lot 8 of
R.W. McCall Allotment

66-25-02-33

R.W. McCall Allotment
P.B. 9, Pg. 59

S 12° 13' 43" E
35.34'

Union Township Road No. 636

The Muskingum College
DR 524-109

N 69° 58' 45" E
187.91'

William Jr. & Naomi J.
Gingerich
DR 663-94
+ 0.87 ac.

$\Delta = 2^\circ 24' 58''$
Rad. = 3865.36'
L = 163.00'
Ch = 162.99'
Ch. Brg. = N 03° 02' 07" E

S 80° 16' 15" W
245.26'

J. & S. Bogart
DR 812-160

State Route 83 (60' R/W)

LEGEND

- ⊙ Iron Pin Set, 5/16" rebar
- Iron Pin Found
- Iron Pipe Found
- ⊙ Aisle Found
- ⊕ R/W Monument
- Stone

SECTION 2
SECTION 1



REFERENCES

DR 663-94
DR 812-160
DR 524-109
DR 976-244
P.B. 9, Pg. 59
Tax Map No. 66-25
State of Ohio R/W Plan - Mus-76-2.73

SITUATED IN

The Township of Union, County of Muskingum,
State of Ohio and being a part of the Northeast
Quarter of Section 2, T-1-N, R-5-W

BASIS OF BEARINGS

Bearings are based on the center line of State Route 83
as depicted on Sheet 1 of 1, of Mus.-76-2.73 R/W Plans.


PARCEL NO.

All of: 66-66-25-02-33-000 (± 0.87 ac.)

OFFICE COPY
NOT RECORDABLE

Jack D. Newcome
Reg. Surveyor No. 7321

11-9-92
Date



Lion Engineering, Inc.
Civil Engineering Consultants
P.O. Box 2621, Columbus, Ohio 43261-0261

614-452-7111