66-80-04-05 PS 66-80-04-07 PS 66-80 18-04 66-80-2362 PS

Situated in the State of Chio, County of Muskingum, Township of Union:

Being a part of Lot Fifteen (15), and Lot Sixteen (16) in Quarter Township Four (4), Township One (1), Range Five (5) and the Southwest Quarter of Fractional Section Eighteen (18), and the Northwest Quarter of Fractional Section Twenty Three (23) of the United States Military Lands and part of the same property owned by the Hardesty Heirs and Recorded in Deed Book 1013, Page 47 of the Muskingum County Deed Records bounded and described as follows:

Reginning at an iron pin set at the northwest corner of Lot 15; thence S 89 05 25 E (the base of bearings for this description is state plane grid from an observation of the sun ) along the morth line of said Lot 15 and the south line of property owned by Beula Dickson (Vol.623, Pg. 172) a distance of 1310.64 feet to a stone found; thence -8/2/29/05 W. along the west line of property owned by Patton Farms, Inc. (Vol. 780, Pg. 265) a distance of 2647.50 feet to an iron pin set on the south line of Lot 15 and the morth line of Lot 16; thence N 87 48 58 W. along said Lot 41.80 feet to an iron pin set at the northwest corner of a 25 acre parcel owned by said Patton Farms, Inc.; thence S 14 09 06 W along the west line of said 25 acre parcel 792.58 feet to an iron pin set at the southwest corner of said parcel; thence N 88 59 04 W along the north line of a 17.00 acre parcel owned by said Patton Farms, Inc. 198.00 feet to an iron pin set; thence S 21 0) 15 W along the west line of said 17.00 acre parcel and the west line of property owned by Elmer and Darlene Lentz (Vol.837,Pg.205) a distance of 530.25 feet to an iron pin set; thence S 11 03 27 W along the west line of said Lentz property 577 50 feet to an iron pin set; thence S 2 33 27 W along the west line of said Lentz property 841.50 feet to an iron pin set in a broken corner stone at the southwest corner of said Lentz property and passing through an iron pin set at 405.05 feet; thence  $\,$  N 88 04 32  $\,$   $\!$   $\!$ along the north line of a 68.00 foot strip of ground owned by William and Ruth Todd (Vol.471, Pg. 386) a distance of 687.41 feet to an iron pin set on the west line of said Lot 16 and the east line of the northwest quarter of fractional section 23; thence 8 2 31 39 W along the east line of said quarter 144.23 feet to an iron pin set at the southeast corner of said northwest quarter; thence N 87 40 40 W along the south line of said northwest quarter of section 23 and the north line of property owned by Larry and Vicki Frick (Vol.811, Pg. 28) a distance of 398.47 feet to a drill hole in the contrete dack of a bridge over a stream on Hardesty Road, said drill hole is 4.50 feet south of the north end of said bridge and passing through an iron pin set at 292.47 feet; thence following the center of said road the following thirteen courses and distances:

- 1- N 21 46 26 W 371.24 feet to an iron pin set, said pin bears S 31 34 37 E 64.52 feet from an iron pin set
- 2- N 09 46 05 W 121 84 feet to an iron pin set
- 3- N 01 42 26 E 327.05 feet to an iron pin set, said pin bears S 09 02 49 W 82.22 feet from an iron pin set
- 4- N 08 01 07 W 187.59 feet to an iron pin set
- 5- N 20 19 52 W 357.73 feet to an iron pin set
- 6- N 10 44 00 W 129,9) feet to an iron pin set, said pin bears S 24 12 10 E - 30.79 feet from an iron pin set