

Situated in the County of Washington, Township of Washington, Township 1, Range 2, of Northwest Quarter of Section 10, Township 1, Range 2, Southwest Quarter of Section 10, Township 1, Range 2, North of Section 10, Township 1, Range 2, being further described as follows:

Commencing at an existing iron pin at the southeast corner of said Section 10, and running South 89° 55' 00" West, 624.63 feet to an iron pin found at the northwest corner of a 2.107 acre tract to be conveyed in the future;

- thence, North 02° 04' 47" West, 3,060.48 feet across the lands of T. and E. Bednarzuk--Deed Book 580, Page 201, to an iron pin (set) at a point on the south line of P. Burwell--Deed Book 177, Page 246,
- thence, North 89° 55' 00" East, 965.64 feet with the south line of said P. Burwell, to an iron pin found at the northwest corner of B. Bowden--Deed Book 214, Page 89,
- thence, South 00° 12' 06" West, 1,916.47 feet to an iron pin (found) at the northeast corner of T. and E. Bednarzuk, Deed Vol 546, Page 227, and passing iron pins (found) at 705.35 feet at the northwest corner of G. Metcalf--Deed Book 993, Page 335, and 1,149.39 feet at the northwest corner of E. Larbaugh--Deed Book 428, Page 363,
- thence, South 89° 55' 00" West, 624.63 feet to a point at the northwest corner of a 2.107 acre tract to be conveyed in the future,
- thence, South 02° 04' 47" West, 333.30 feet along the west line of said 2.107 acre tract to a point in the center of Culbertson Road (Twp. 24, N. 2, W. 2) passing iron pins (set) at 3.00 feet and 313.30 feet,
- thence, South 75° 41' 14" East, 287.25 feet with the center-line of said Culbertson Road, to a point,
- thence, South 73° 50' 10" East, 422.58 feet with the center-line of said Culbertson Road to a point at the northwest corner of X. Steve--Deed Book 212, Page 16,
- thence, South 00° 18' 17" East, 1,000.03 feet with the west line of the said X. Steve and the west line of the Circle E Estates--Deed Book 15, Page 55, to an existing iron pin at the southwest corner of said Circle E Estates, passing an existing iron pin at 15.00 feet,