

- #9- **THENCE South 62 degrees 07 minutes 13 seconds East 219.53 feet** continuing along said road and properties to an unmarked point;
- #10- **THENCE along a curve to the left having, a chord bearing South 65 degrees 24 minutes 20 seconds East 237.20 feet, a radius of 2069.63 feet,** and arc length of 237.33 feet continuing along said road and properties to an unmarked corner of the Gary L Tysinger property recorded in Deed Book Volume 750, Page 348;
- #11- **THENCE South 10 degrees 54 minutes 16 seconds West 175.72 feet** leaving said road and along a common line for said Fuller and Tysinger properties to an iron pipe (found), passing an iron pipe (found) at 22.76 feet;
- #12- **THENCE South 05 degrees 04 minutes 14 seconds East 304.87 feet** continuing along said properties to an iron pin (set) at the center of said Section 6;
- #13- **THENCE North 87 degrees 28 minutes 08 seconds West 2270.84 feet** along the common line for the Northwest and Southwest Quarters of Section 6 to an unmarked corner of the Robert D Fuller Jr. and Donna J Fuller property recorded in Deed Book Volume 966, Page 243, passing an iron pin (set) at 2217.67 feet;
- #14- **THENCE North 18 degrees 04 minutes 29 seconds East 31.45 feet** into said Northwest Quarter of Section 6 and along said Fuller properties to an iron pin (found);
- #15- **THENCE North 36 degrees 41 minutes 39 seconds West 119.94 feet** continuing along said Fuller properties to an iron pin (found);
- #16- **THENCE North 72 degrees 26 minutes 37 seconds West 99.25 feet** continuing along said Fuller properties to an iron pin (found);
- #17- **THENCE North 88 degrees 42 minutes 05 seconds West 195.31 feet** continuing along said Fuller properties to an unmarked point on the common line for said Sections 1 and 6 also for said Ranges 12 and 13, further being in the roadbed of Millers Lane, passing an iron pin (set) at 167.43 feet;
- #18- **THENCE North 01 degrees 52 minutes 45 seconds East 642.13 feet** along said Range and Section line to an iron pin (set) at the common corner for the Northeast and Southeast Quarters of said Section 1;
- #19- **THENCE North 87 degrees 08 minutes 52 seconds West 171.60 feet** along the common line for said Northeast and Southeast Quarters of Section 1 to an iron pin (set) at a corner of the Larry McCutcheon and Sandra J McCutcheon property recorded in Official Record Volume 2219, Page 752, passing the centerline of said Millers Lane at 30.80 feet;
- #20- **THENCE North 01 degrees 26 minutes 11 seconds East 382.68 feet** into said Northeast Quarter of Section 1 and along said Fuller and McCutcheon properties to the common corner of the Richard E Dodson and Linda S Dodson property recorded in Deed Book Volume 1052, Page 510, and for the Danny E Jewell and A Diane Jewell property recorded in Official Record Volume 1940, Page 676, further being in the intersection of Millers Lane and Clay Pike, passing an iron pin (set) at 320.00 feet;
- #21- **THENCE South 16 degrees 55 minutes 42 seconds East 177.41 feet** along the centerline of Clay Pike and said Fuller and Jewell properties to an unmarked corner of a second Danny E Jewell and Diane Jewell property recorded in Official Record Volume 2652;
- #22- **THENCE South 20 degrees 10 minutes 30 seconds East 85.98 feet** continuing along said road and second Jewell property to an unmarked point;
- #23- **THENCE South 86 degrees 58 minutes 29 seconds East 110.82 feet** continuing along said second Jewell property and leaving said road to an iron pin (set), passing an iron pin (set) at 21.00 feet and into Section 6 at 85.07 feet;
- #24- **THENCE North 03 degrees 01 minutes 31 seconds East 213.50 feet** continuing along said second Jewell property to an unmarked point in the centerline of Clay Pike, passing an iron pin (set) at 188.67 feet;

