ALAN DONAKER SURVEYING

Alan Donaker, P.S. 19849 TR 383 Walhonding, OH 43843 Phone: (740) 327-7001

Fax: (740) 327-1083

Being 124.411 acres, more or less, in Sections 4, 6 and 7, Second Quarter, Township 2 North, Range 8 West, United States Military Lands, in the Township of Muskingum, in the County of Muskingum, in the State of Ohio, conveyed to Marcelene H. Cooper, DR 1688-656 (part) and DR 991-463 (part), Parcel No. 44-02-04-15-000 (all, 46.257 acres), Parcel No. 44-02-07-04-000 (all, 76.608 acres) and Parcel No. 44-02-06-19-000 (all, 1.546 acres) and more particularly described as follows:

Commencing at a %" rebar found at the Northeast corner of the Northwest Quarter of Section 7, said rebar being the TRUE POINT OF BEGINNING;

thence, with the property line of Marcelene H. Cooper, DR 1688-656 (third parcel), S. 00° 31' 28" E. a distance of 835.71' to a \%" rebar found;

thence, with the property line of Ronald F. Moran, DR 884-320, S. 00° 03' 58" E. a distance of 531.31' to a %" rebar found;

thence, with the property line of Timothy A. and Lori Ann Thacker, DR 1910-244, the following 3 courses:

- 1. thence, S. 89° 52' 06" W. a distance of 2082.81' to a %" rebar found;
- 2. thence, N. 00° 03' 58" W. a distance of 57.55' to a 1/8" rebar found;
- 3. thence, S. 79° 56' 02" W. a distance of 184.18' to a 5%" rebar found;

thence, with the property line of Robin Gary and Dorene Joyce Baker, DR 1060-320, the following 6 courses:

- 1. thence, N. 16° 36' 08" E. a distance of 70.81' to a 1/2" pipe found;
- 2. thence, S. 89° 57' 16" W. a distance of 142.30' to a ½" pipe found;
- 3. thence, S. 89° 26' 56" W. a distance of 196.68' to a 1/2" pipe found;
- 4. thence, S. 88° 46' 10" W. a distance of 75.38' to a %" rebar set;
- 5. thence, S. 88° 49' 54" W. a distance of 156.50' to a 1/2" pipe found;
- 6. thence, S. 87° 45' 56" W. a distance of 41.45' to a point in the centerline of Fawn Drive (Township Road 37);

thence, with the centerline of Fawn Drive (Township Road 37) and the property line of Trudy D. and James E. Reed, DR 1763-678, the following 2 courses:

- 1. thence, N. 06° 24' 35" W. a distance of 184.70' to a point;
- 2. thence, N. 10° 14' 57" W. a distance of 108.18' to a point;

thence, with the property line of Donald Joseph Quinn, DR 1144-260, the following 3 courses:

- 1. thence, N. 76° 38' 06" E. a distance of 14.12' to a %" rebar found;
- 2. thence, N. 76° 38' 06" E. a distance of 256.81' to a %" rebar found;
- 3. thence, N. 25° 08' 48" E. a distance of 481.39' to a $\frac{5}{8}$ " rebar found;

thence, with the property line of Kent Thomas & Wendy Jane Burkhart, DR 1144-268, the following 2 courses:

- 1. thence, N. 80° 46' 12" E. a distance of 133.23' to a %" rebar found;
- 2. thence, N. 10° 56' 20" W. a distance of 1287.75' to a %" rebar found;

thence, with the property line of Farm Supply Center, Inc., DR 948-26 and Cecil C. Jordan, DR 761-268, N. 89° 13' 11" E. a distance of 2511.07' to a %" rebar set;

thence, with the property line of Cecil C. Jordan, DR 761-268, the following 3 courses:

- 1. thence, N. 89° 13' 11" E. a distance of 5.00' to a wood post found;
- 2. thence, S. 01° 09' 48" E. a distance of 5.00' to a %" rebar set;
- 3. thence, S. 01° 09' 48" E. a distance of 816.56' to the TRUE POINT OF BEGINNING, containing 124.411 acres, more or less, including public road right-of-way and is subject to all easements, rights-of-way, or restrictions, whether recorded or implied.

Bearings are based on OR 1688-656 (parcel 3) and are for angular calculations only.

All 5/8" rebars set are 30" long with plastic cap marked "AMD 8050".

Pertinent Documents: Tax Map and all Deeds shown.

Flood Plain panel #390425 0040 C, Zones A and X

YOT RECORDABLE

1/1/2/2/6/LU)L

Surveys by: Earl R. Donaker, Stephen M. Bowman, L. Peter Dinan, Richard Max Graves

Description and plat by Alan Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from a survey of the premise Landon Donaker, Professional Surveyor, #8050, from the premise Landon Donaker, Professional Surveyor, Professional Surv

OF

ALAN

CONAKER

Page 2 of 2

