

SITUATED IN

The State of Ohio, County of Muskingum,
Township of Newton, and being a part of
the North Half of Section 19, T15N, R14W,
U.S.M.L.

BASIS OF BEARING

Bearings are based on NAD 83 State Plane
Grid Coordinate System as per GPS Observations.

REFERENCES

DR 439-350
DR 702-345
DR 776-29
DR 983-79
DR 1034-235
Moore's Subdivision, P.B. 4, Pg. 147

M.R.W.D.
DR 1089-439

Monument Found at the NE
Corner of the NW Quarter of
Section 19, Newton Township,
Muskingum County, Ohio,
T15N, R14W, U.S.M.L.

LINE	BEARING	DISTANCE
L0	S49°34'37"W	34.70'
L1	S84°27'40"W	81.75'
L2	S80°04'31"W	58.47'
L3	S87°38'20"W	58.47'
L4	S89°24'13"W	58.48'
L5	S73°20'38"W	58.50'
L6	S89°38'43"W	58.58'
L7	S78°33'12"W	58.61'
L8	S78°32'56"W	64.56'
L9	N05°16'35"E	150.49'
L10	S77°08'23"W	131.13'
L11	S78°04'38"W	131.15'
L12	S77°39'31"W	131.85'
L13	S14°45'41"E	132.00'
L14	S81°25'34"W	62.00'
L15	S12°30'29"E	132.00'
L16	N80°04'51"E	57.00'
L17	S88°32'21"W	82.20'
L18	N10°12'35"W	132.00'
L19	N67°38'20"E	57.00'

M.R.W.D.
DR 1089-439

Note: Iron Pin Set on true
corner of T. Carson land.
Monument called for by my
previous survey, but was set in
wrong location.

Shirley Moore Baille
and Leslie Moore
DR 702-345
±40.37 Ac.

NE Corner of Lot 10
Moore's Subdivision
P.B. 4, Pg. 147

±3.95 Ac.

PARCEL NOS.

of: 47-47-38-19-02-000 (± 3.95 Ac.)
of: 47-47-56-01-09-000 (±40.37 Ac.)
of: 47-47-56-01-11-000 (± 0.17 Ac.)
of: 47-47-56-01-12-000 (± 0.18 Ac.)
Total = ±44.67 Ac.

LEGEND

- ☒ Monument Found
- Stone Found
- Concrete Post
- Iron Bolt Found
- Iron Pipe Found
- Iron Pin Found
- Iron Pin Set, 5/8" rebar
w/ Plastic ID Cap

GRAPHIC SCALE

(IN FEET)
1 inch = 200 ft.

**OFFICE COPY
NOT RECORDABLE**

Jack D. Nowell
Reg. Surveyor No. 732

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY 5-29-98

Date

Project No.: MRWD-986



Linn Engineering, Inc. 740-452-7434
Civil Engineering Consultants
P.O. Box 2086 Xenia, Ohio 45302-2086