

SNR

Part of Mary Spring Property  
Vol. 924, Page 291  
2/29/96

Situated in the State of Ohio, County of Muskingum, Township of  
Newton, Township 15, Range 14, Section 26, bounded and described as  
follows:

Commencing at an axle found at the Southwest corner of the Southwest  
Quarter of Section 26; thence North  $0^{\circ} 21' 15''$  East on quarter section  
line 2106.17 feet to an iron pin set; thence leaving section line  
North  $89^{\circ} 44' 43''$  East ~~270.75~~ <sup>The Place of Beginning is</sup> feet to an iron pin; thence North  
 $89^{\circ} 44' 43''$  East along David Miller, Vol. 531, Page 719, 485.00 feet  
to an iron pin set; thence along the split  
lines of Mary Spring, Vol. 924, Page 291, the next four (4) courses  
and distances, South  $0^{\circ} 35' 05''$  West 392.83 feet to an iron pin set,  
South  $53^{\circ} 50' 15''$  West 295.68 feet to an iron pin set, South  $62^{\circ} 57' 15''$   
West 285.11 feet to an iron pin set and North  $0^{\circ} 57' 42''$  East 694.87  
feet to the place of beginning, containing 6.23 acres more or less.

Being part of Auditor's Parcel No. 47-94-26-14-000.

Bearings are based on the West line of Northwest Quarter of Section 26  
bearing North  $0^{\circ} 21' 15''$  East.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic  
I. D. caps.

Reference: Volume 924, Page 291.


Survey & Description By:

**OFFICE COPY  
NOT RECORDABLE**

R. L. Daniels  
Registered Surveyor No. 5410

DESCRIPTION APPROVED  
FOR AUDITORS TRANSFER

BY MSH  
2-29-96



SNR

Part of Mary Spring Property  
Vol. 924, Page 291  
2/29/96

Situated in the State of Ohio, County of Muskingum, Township of Newton,  
Township 15, Range 14, Section 26, bounded and described as follows:

Commencing at an axle found at the Southwest corner of the Southwest  
Quarter of Section 26; thence North  $0^{\circ} 21' 15''$  East on quarter section  
line 2106.17 feet to an iron pin set; thence leaving section line North  
 $89^{\circ} 44' 43''$  East ~~812.83~~ to an iron pin, the place of beginning; thence  
along David Miller, Vol. 531, Page 719, North  $89^{\circ} 44' 43''$  East 457.32  
feet to an iron pin set; thence along split lines of Mary Spring the  
next four (4) courses and distances, South  $0^{\circ} 57' 42''$  West 694.87 feet  
to an iron pin set, North  $88^{\circ} 59' 45''$  West 242.95 feet to a point, South  
 $81^{\circ} 16' 24''$  West 198.86 feet to an iron pin set and North  $39^{\circ} 40' 22''$   
East 201.34 feet to an iron pin found; thence along R. Holshuer,  
Vol. 737, Page 201, North  $13^{\circ} 27' 17''$  West 579.00 feet to the place  
of beginning, containing 6.10 acres more or less.

Being part of Auditor's Parcel Number 47-94-26-14-000.

Bearings are based on the West line of Northwest Quarter of Section  
26 bearing North  $0^{\circ} 21' 15''$  East.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic  
I. D. caps.

Reference: Volume 924, Page 291.

Survey & Description By:

**OFFICE COPY**  
**NOT RECORDABLE**

Registered Surveyor No. 5410

DESCRIPTION APPROVED  
FOR AUDITORS TRANSFER

BY atd  
2-29-96



1"=100'

David Miller 531-719

M. Spring  
924-291

$50^{\circ}35'05''W$   
392.83

$S53^{\circ}50'15''W$   
295.68

$S62^{\circ}57'15''W$   
285.11

6.23Ac

$N0^{\circ}57'42''E$   
694.87

6.10A

DESCRIPTION APPROVED  
FOR AUDITORS TRANSFER

BY RLD  
2-29-96

$N88^{\circ}52'45''W$   
242.95

$S81^{\circ}16'24''W$   
198.86

$N39^{\circ}40'22''E$   
201.34

$N13^{\circ}27'17''W$   
579.00

R Holshuer  
737-201

- o Iron Pins Found
- Iron Pins Set No 5 Rent Bars 30" Lg. Plastic ID. Cap

Mary Spring  
Parcel 47-94-26-14-000  
Muskingum County,  
Newton Twp, T15,  
R14, Sec. 26  
2/29/95  
R.L. D... Rec Surveyor  
No. 5410

OFFICE COPY  
NOT RECORDABLE

$N0^{\circ}21'15''E$   
2106.17

SW 1/4  
Sec. 26

$N89^{\circ}44'43''E$

812.83

457.32

485.00