in the State of Ohio, County of Muskingum, Township of Falls:

and Being part of the 4th Quarter Township, Township #1, Range #8, of the US Military District, being a proposed partial vacation of the right of way for Arrow Point Drive Township Road #1239, more particularly described as follows;

Beginning at an iron pin (set) at the Northwest corner of Lot #15 of Dillon Falls Drive No 2 recorded in Plat Book 8, Page 49: Book 8, Page 49;

- **THENCE South 14 degrees 07 minutes 35 seconds East 76.00 feet** along common line for said lot and right of way to an unmarked point at a common corner for the Kay E Dozer property recorded in Official Record Volume 1843, Page 844 and for the Harold V & Fay A Luke property recorded in Deed Book Volume 465, Page 448; Dozer property
- #2-THENCE South 80 degrees 35 minutes 00 seconds West 60.09 feet crossing said right of way to an iron pin (found) at a common corner for the Kay E Dozer property recorded in Official Record Volume 1843, Page 845, and for the Christopher L & Tina R Quinlan property recorded in Deed Book Volume 1121, Page 59;

 THENCE North 06 degrees 33 minutes 20 seconds West 78.36 feet along said Dozer
- #
- # property and said right of way to an iron pin (set);
 THENCE North 83 degrees 28 minutes 05 seconds East 50.00 feet continuing along said
 Dozer property and said right of way to the place of beginning, containing 0.10 acres.

RESERVING AN EASEMENT FOR INGRESS AND EGRESS

particularly described as follows; in connection with an easement recorded in Official Record Volume 1824, Page 556, and more Reserving an easement for ingress and egress over a portion of the above described vacation

Beginning at an iron pin (set) at the Northwest corner of Lot #15 of Dillon Falls Drive No 2, recorded in Plat Book 8, Page 49;

E1- THENCE South 14 degrees 07 minutes 35 seconds East 76.00 feet along common line for

- said lot, right of way, and recorded easement to an unmarked point at a common corner for the Kay E Dozer property recorded in Official Record Volume 1843, Page 844 and for the Harold V & Fay A Luke property recorded in Deed Book Volume 465, Page 448;
- E2an unmarked point; THENCE South 80 degrees 35 minutes 00 seconds West 30.00 feet into said right of way to
- Ęζ recorded easement; right of way to an unmarked point on the common line for right of way and for the Kay E property recorded in Official Record Volume 1843, Page 845 also being a corner of said THENCE North 04 degrees 19 minutes 20 seconds West 76.90 feet continuing through said Dozer
- **E4**-Dozer property, and recorded easement to the place of beginning. THENCE North 83 degrees 28 minutes 05 seconds East 16.95 feet along said right of way

GPS The bearings within this description are based on State Plane Coordinate Grid derived from a Observations. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

indicated does not intend to describe all or any easements of record, nor encroachments unless otherwise actual survey completed on January 15, 2004, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and This description was written by Charles R. Harkness Professional Land Surveyor #6885 from January 15, 2004, in accordance with Chapter 4733-37 of the

Charles ָת Harkness PLS #6885



FOR MANY 띳

