

44.00
NW Cor
NW Qtr Sec 4
26
27
28
29

OFFICE COPY
NOT RECORDABLE

Center of Johnson Hill Road

17.76
2.21
20.00
43
63.00

50°55'33"W 1959.16
1919.16

64.81 AC.

Center
Dozer Road

ID Found
52.8

ID Found N 84°19'52"E 756.58
789.45

Conc Mon.
Found
S 88°15'29"E
446.71

S 1°59'43"W
626.25

Conc Mon.
Found

S 88°26'46"E
868.86

ID Found

N 32°43'E
1228.59

- 1-4 N 41°06'02"W 114.27
- 4-5 N 35°27'44"W 86.54
- 5-6 N 42°52'12"W 60.31
- 6-7 N 57°52'01"W 48.07
- 7-8 N 75°04'46"W 61.13
- 8-9 N 77°40'32"W 331.37
- 9-10 N 74°27'59"W 55.04
- 10-11 N 66°13'31"W 30.68
- 11-16 N 66°31'56"W 58.43
- 16-15 N 54°32'15"W 66.36
- 15-14 N 45°17'40"W 61.95
- 14-13 N 42°44'26"W 159.81
- 13-20 N 45°12'48"W 153.88
- 20-19 N 51°13'W 70.98
- 19-18 N 53°48'22"W 82.22
- 18-17 N 56°42'33"W 205.43
- 17-22 N 57°08'33"W 260.08
- 22-29 N 58°01'47"W 311.53
- 29-28 N 55°18'W 87.48
- 28-27 N 53°20'20"W 92.25
- 27-26 N 51°26'58"W 92.47
- 26-51 N 47°08'20"W 59.30

Survey
Alice A
Proper
BTRLL
No 5410
Muski
Brush
TIO, R
All of
08-08-
08-08-
08-08-

TENANCY IN THE GRANTEEES PURSUANT TO SECTION 5302.17 OHIO REVISED