

DESCRIPTION
APPROVED

[Signature] 9/9/2016

EXHIBIT "B"

Beginning at the southeast corner of Lot 1 in Ollies Subdivision as recorded in Plat Book 9, Page 66; thence along the east line of said Lot 1 north 50.34 feet to an iron pin placed; thence east 45.0 feet to a point; thence north 14 degrees 54 minutes 32 seconds east 81.53 feet to a point; thence south 78 degrees 04 minutes 10 seconds east 105.0 feet to a point; thence south 12 degrees 26 minutes 45 seconds west 110.0 feet to a point; thence west 145.0 feet to the place of beginning, containing thirty-five hundredths (0.35) of an acre.

Restrictions for the use of the above described easement.

This description written from a survey made by L. Peter Dinan, Registered Surveyor #5451, August 31, 2016.



ST. MARYS ROAD

ST MARYS CHURCH
D.B. 52, P. 459

LOT 1
JAMES A. GRIFFIN
BISHOP OF COLUMBUS
DIOCESE OF COLUMBUS
D.B. 940, P. 177

EXHIBIT "A"
0.03 ACRES
MATINGLY CEMETERY ASSOCIATION
DEED BOOK 985, PAGE 272
PARCEL # 44-14-02-22-002, PART OF

EXHIBIT "B"
EASEMENT FOR
PROPOSED SEWAGE
TREATMENT SYSTEM
0.35 AC.

N

1"=50'

⊗ IRON PIN (AXLE) FOUND
● IRON PIN SET

SOUTHWEST CORNER
LOT 1, OLLIES SUB.

SOUTHEAST CORNER
LOT 1, OLLIES SUB.
PLAT BOOK 9, PAGE 66

LOT 2, OLLIES SUBDIVISION
PLAT BOOK 9, PAGE 66
RALPH WEAVER
D.B. 1986, P. 267

STEVEN & MARLA RICE
D.B. 1592, P. 133

PART OF LOT 14
QTR. TWP. 3, TWP. 2, RA. 8
IN MUSKINGUM TOWNSHIP
MUSKINGUM COUNTY, OHIO
AUG. 12, 2016

DESCRIPTION
APPROVED

9/9/2016



OFFICE COPY
NOT RECORDABLE

REGISTERED SURVEYOR #5451