SITUATED IN ReSurvey The State of Ohio, County of Muskingum, Township of Salem, being part of the North Half of the Southwest Quarter of Section 8, T2, R6, United States Military Lands. BASIS OF BEARING Bearings are based on State Plane Grid Coordinates, NAD83, Ohio South, per GPS Observation. RUTH C. KNICELY & RICHARD KNICELY, TRUST. @18.11 5/8" @247.15' VERNON & BOL OR 2932-57 dinan Unmarked Point Iron Pin Set dinan Iron Pin Found f.o.p. \boxtimes Stone Found Property Hook SEE DETAIL A ROBERT BRYCE f.o.p. Found Out Of Position **E** KNICELY ROAD (TR-356) DETAIL 200 PR 136 27 N.T.S. All of: 56-50-08-14-000 ELIZABETH A. DARNER 5/8" OR 3074-330 ±10.432 Ac. GRAPHIC SCALE REFERENCES (IN FEET) dinan * As Noted on Plat 1 inch = 150 ft.www.muskingumcountyauditor.org 0 www.mceo.org half 0 http://recorder.muskingumcounty.org Section & Previous surveys by: Dinan, 2009 & 2020 Graves, 1994 the, of LINE TABLE corner of the Stone SE cc the cc dinan @195.13

LINE	BEARING	DISTANCE
L1	N 60°57'04" W	717.87
L2	N 56°46'30" W	81.45
L3	N 59°20'16" W	78.41
L4	N 10°59'36" W	125.70'
L5	S 02°11'30" W	103.53
L6	S 06'16'39" E	124.82'
L7	S 88'44'19" E	3.47'

CURVE TABLE

OFFICE COPY

This plat was prepared by McPeek Land Surveying, LLC in accordance with Chapter 4733—37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise intended.



www.mcpeeklandsurveying.com LLC
email: brian@mcpeeklandsurveying.com
1705 East Pike,* Zanesville, Oh 43701 * 740.704.6073