

Mrs. Donald Ullman, Sr.
from
H. Richard Greiner
7/1/90

SNR

Situated in the State of Ohio, County of Muskingum, Township of Springfield, Township 16N, Range 14W, Section 17, and bounded and described as follows:

Commencing at a stone found at the Southeast corner of Section 17; thence North $2^{\circ} 43' 08''$ East 377.95 feet to an iron pin at the South corner of Donald E. Ullman, Jr.; thence along Ullman's West line North $23^{\circ} 05' 26''$ West 1328.23 feet to an iron pin found on the South side of Township Road 90 (above location from section corner from description by George W. Stewart, Registered Surveyor No. 6357); thence from said iron pin found North $37^{\circ} 43' 59''$ East 41.12 feet to a point in the center of Township Road 90; thence North $16^{\circ} 01' 27''$ West 176.22 feet to an iron pin set, the place of beginning; thence along Phillip and LaDonna Trout South $69^{\circ} 08' 12''$ West 52.03 feet to an iron pin set; thence along H. Richard Greiner, Vol. 540, Page 705, the following four (4) courses and distances, North $16^{\circ} 01' 27''$ West 122.46 feet to an iron pin set, North $74^{\circ} 21' 46''$ East 178.36 feet to an iron pin set, South $70^{\circ} 22' 52''$ East 278.66 feet to an iron pin set and South $1^{\circ} 12' 26''$ West 27.74 feet to an iron pin found on Larry Bee's, Vol. 546, Page 867, Northwest corner; thence along Larry Bee South $4^{\circ} 31' 18''$ West 133.65 feet to the center of Township Road 90 passing an iron pin found at 108.65 feet; thence along the center of Township Road 90 South $86^{\circ} 53' 48''$ West 91.80 feet to a point; thence leaving Township Road 90 and along Donald Ullman, Sr., Vol. 1008, Page 338, the following three (3) courses and distances, North $15^{\circ} 51' 27''$ West 215.00 feet to an iron pin found, South $74^{\circ} 05' 33''$ West 209.00 feet to a point and South $16^{\circ} 01' 27''$ East 38.78 feet to the place of beginning, containing 1.023 acres more or less.

Bearings are based on survey by George W. Stewart, Registered Surveyor No. 6357.

Part of Parcel Number 62-62-39-01-32-000.

Iron pin set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.

Deed Reference: Volume 540, Page 705.

OFFICE COPY
NOT RECORDABLE
Survey & Description By:
R. L. Daniels
R. L. Daniels
Registered Surveyor No. 5410

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY *J. L. Nambel*
7-19-90

BY J. L. Rasmussen
7-19-90