

66-01-05-12-000 B

Northeast Corner of the
Southeast Quarter of Section
5, T 1, R 5, U. S. M. L.

Surveyor's Note
The Section Line between Sec. 4, and
Sec. 5, has several pins found along
the line, but do not make a straight
line, and from the older deeds, the
pins were set in the fence line. This
action started approx. fifty years
ago, and the properties adjoining
them have acquiesced to the lines as
per the pins found.

SITUATED IN:
State of Ohio, County of Muskingum, Township of Union,
and being part of the Southeast Quarter of Section 5,
Township 1, Range 5, United States Military Lands

BASIS OF BEARINGS

Bearings are based on the Ohio State Plane
Coordinate System, NAD 83, South Zone, Grid North,
as per GPS observations.

REFERENCES

All Official and
Deed Records
shown on this
plat.

PARCEL NO.S

All of: 66-01-05-12-000 +- 88.20 Acres
All of: 66-01-05-13-000 +- 0.17 Acres

LEGEND

- △ Railroad Spike Set
- Iron Pin Found
- ⊕ Stone Found
- Axle Found
- Iron Pipe Found
- ▲ Railroad Spike Found
- ⊙ Iron Pin Set, 5/8" rebar
- ⊠ Monument Found

COURSE	BEARING	DISTANCE
L-1	N 85°31'40"W	64.40'
L-2	N 78°42'13"W	45.88'
L-3	N 78°48'09"W	57.86'



OFFICE COPY


NOT RECORDABLE

Jack D. Newcome

Date

Reg. Surveyor No. 7321

Newcome Surveying Company
6515 Ballard Road
Nashport, Ohio
740-452-5798



**DESCRIPTION
APPROVED**

By: *[Signature]*

Michael Paul and
Shelly Amanda Sowers
Trustees
OR 2284-375

George G. and
Hilda Pappas
Trustees
OR 1804-921
DR 638-24
+- 88.37 Acres

William K. and
Marilyn R. McKelvey
DR 675-259

Leo and Debra D.
Buechner
DR 1077-276

Pidcock Road, (Twp.
Rd. 440)

Larry L. and Sandra
J. Blackwood
DR 1148-632
DR 576-932

Andrew H. and
Marcie L. Blackwood
OR 2258-663
DR 1148-259
OR 2197-227

James L. and
Carolyn K. Blackwood
DR 1143-789

Gregory J. and Michael R. Connell
DR 1071-572

Mathew R. Connell
OR 2591-962

Donald E. and
Carolyn S. Green
OR 1852-86

Stephen and
Cindy Burkhardt
OR 1973-167

Sec. 5 Sec. 4
Sec. 6 Sec. 7