

Re-Survey of New Concord Cemetery Association Lands

Situated in the State of Ohio, County of Muskingum, Township of Union, and being part of Section 2, Township 1, Range 5, United States Military Lands, and being all the lands presently owned by the New Concord Cemetery Association, as per Official Record 1142, Page 165, and Deed Records, 160, Page 63, 148, Page 599, 156, Page 357, 161, Page 461, and 203, Page 490, and being more particularly described as follows:

Beginning for reference at a stone found at the southeast corner of the Northeast Quarter of Section 2, Township 1, Range 5, United States Military Lands;

Thence along the mid -section line, South 87 degrees 25 minutes 26 seconds East, 110.36 feet to a point in the centerline of State Route 83,(Friendship Drive), and being the principal place of beginning;

Thence along the centerline of said road the following four courses:

- 1.) South 15 degrees 46 minutes 02 seconds East, 43.81 feet to a point;
- 2.) South 13 degrees 32 minutes 32 seconds East, 90.80 feet to a point;
- 3.) South 11 degrees 38 minutes 19 seconds East, 59.82 feet to a point;
- 4.) South 09 degrees 46 minutes 36 seconds East, 45.29 feet to a point on a corner of lands presently owned by Justin Michael Sawyer,(OR 2251-190);

Thence along the lines of said Sawyer lands the following four courses:

- 1.) South 74 degrees 12 minutes 51 seconds West, 359.87 feet to an iron pin found, passing an iron pin set at 28.11 feet;
- 2.) North 76 degrees 34 minutes 48 seconds West, 220.73 feet to an iron pin found;
- 3.) North 41 degrees 54 minutes 15 seconds West, 171.65 feet to an iron pin found;
- 4.) North 43 degrees 07 minutes 48 seconds East, 73.31 feet to an iron pin found on the southwest corner of lands also presently owned by Justin M. Sawyer,(OR 2488-210);

Thence along the lines of said Sawyer lands the following two courses:

- 1.) North 49 degrees 28 minutes 12 seconds East, 86.95 feet to an iron pin found;
- 2.) North 05 degrees 21 minutes 15 seconds East, 188.94 feet to an iron pin set on the south line of lands presently owned by Mark F. and Teresa A. McCabe,(OR 1145-821);

Thence along the south lines of said McCabe lands the following two courses:

- 1.) North 83 degrees 45 minutes 18 seconds East, 116.81 feet to an iron pin found;
- 2.) North 67 degrees 47 minutes 07 seconds East, 305.82 feet to a point in the centerline of State Route 83,(Friendship Drive), passing an iron pin found at 282.33 feet;

Thence along the centerline of said road the following three courses:

- 1.) South 19 degrees 00 minutes 31 seconds East, 151.58 feet to a point;
- 2.) South 17 degrees 58 minutes 17 seconds East, 85.01 feet to a point;
- 3.) South 15 degrees 46 minutes 02 seconds East, 51.65 feet to the principal place of beginning, containing 6.06 acres , more or less, and being all of Auditor's Parcel Numbers, 66-20-02-27-001 +- 1.31 Acres, 66-20-02-26-001 +- 0.68 Acres, and 66-24-01-01-000 +- 4.07 Acres, of which 0.36 acres is in the right of way of State Route 83.

Subject to all legal recorded easements and right of ways.