#### EXHIBIT "D"

### WARD & EMLER SURVEYING, INC.

Professional Land Surveyors 113 Third Street SE New Philadelphia OH 44663-2512 (330) 364-5866 (voice) (330) 364-1107 (fax) E-mail: wesucyey(a,adelphia.net

Samuel C. Ward - P.S.#7356 Randall A. Emler - P.S.#7760

Robert F. Rogai - P.S.#6534

June 15, 2007 Revised July 26, 2007

## Tract 4 Description of a 21.843 Acre Tract For J.J. Detweiler Enterprises, Inc. – Bush Farm

Situated in the Township of Brush Creek, the County of Muskington, the State of Ohio.

Being located in the west and east half of the southwest quarter of Section 9, T-10, R-13 and being part of a 79.39 acre tract – parcel 2 (Parcel No. 0808700916000) and part of a 79.37 acre tract – parcel 1 (Parcel No. 0808700915000) as conveyed to JJ Detweiler Enterprises in Official Record Volume 2093 at Page 538 of the Muskingum County official records with the tract to be conveyed being more fully described as follows:

Commencing at a 5/8" iron pin (set) at the southeast corner of the southwest quarter of Section 9, being also at the TRUE PLACE OF BEGINNING of the tract herein described;

Thence from said beginning and with the southerly line of the east half of said quarter section North 87 deg. 04 min. 52 sec. West, 1322\_39 feet to a stone monument (found) at the southwest corner of said east half;

Thence with the southerly line of the west half of the southwest quarter of Section 9 North 86 deg. 14 min. 42 sec. West, 1235.83 feet to a 5/8" iron pin (set) at the southeasterly corner of a one and a fourth acre tract as conveyed to the Trustees of the Lutherian Church Brush Creek Twp. (Deed Vol. 1, Pg. 419);

Thence with the bounds of said tract the following two (2) courses and distances;

- thence North 3 deg. 45 min. 18 sec. East, 132.00 feet to a stone monument (found) at the northeasterly corner
  of said tract;
- (2) thence North 86 deg. 14 min. 42 sec. West, 82.42 feet to a 5/8" iron pin (set) on the west line of said quarter section and at the northwesterly corner of said tract;

Thence with said westerly line North 3 deg. 47 min. 16 sec. East, 1045.02 feet to a 5/8" fron pin (set);

Thence leaving said line and through the lands of said parent tract South 36 deg. 01 min. 25 sec. East, 717.77 feet to a point at the intersection of "Dozer Ridge Road" and "Bell Hill Road" and passing on line a 5/8" iron pin (set) at 694.86 feet;

Thence continuing through the lands of said parent tract and with "Bell Hill Road" the following ren (10) courses and distances:

- (1) thence South 50 deg. 27 min. 31 sec. East, 163.81 feet to a point;
- (2) thence South 51 deg. 27 min. 50 sec. East, 158.34 feet to a point;
- (3) thence South 56 deg. 07 min. 56 sec. East, 104.22 feet to a point;
- (4) thence South 61 deg. 29 min. 14 sec. East, 84.24 feet to a point;
- (5) thence South 72 deg. 06 min. 01 sec. East, 72.83 feet to a point;
- (6) thence South 78 deg. 54 min. 56 sec. East, 200.92 feet to a point;
- (7) thence South 72 deg. 30 min. 26 sec. East, 103.10 feet to a point;
- (8) thence South 63 deg. 32 min. 24 sec. East, 96.85 feet to a point;
- (9) thence South 56 deg. 45 min. 29 sec. East, 83.94 feet to a point;

(10)thence South 51 deg. 44 min. 13 sec. East, 92.62 feet to a point;

Thence leaving said road and continuing through the lands of said parent tract South 87 deg. 04 min. 52 sec. East, 1142.72 feet to a 5/8" iron pin (set) on the easterly line of the east half of the southwest quarter of Section 9 and passing on line a 5/8" iron pin (set) at 22.08 feet and at 484.13 feet;

Thence with said easterly line South 3 deg. 52 min. 16 sec. West, 150.02 feet to the TRUE PLACE OF BEGINNING, containing 21.843 acres more or less but subject to all legal highways, rights-of-way, easements, leases and restrictions of record or otherwise legally established.

The above-described tract consists of 17.045 acres out of Parcel No. 0808700916000 and 4.798 acres out of Parcel No. 0808700915000.

Bearings herein are oriented to north by GPS observations and all iron pins set are 5/8"x30" iron rebars with orange plastic caps stamped "EMLER 7760".

Survey and description by Randall A. Emler, Professional Surveyor #7760 in May and June of 2007.

APPROYPO FOR CLOSURE

EXEMPT FROM

PLANNING COMMISSION

Randall A. Emier

Professional Surveyor #7760

This property is located in Zone X as shown on Coomunity Panel #390425 0175 C effective date time 3, 1988 of the Flood Insurance Rate Maps and is not in a special flood hazard area as determined by graphic methods only. 20.00 APAROYÉOÆOR CLOSURE This property is subject to all legal high ways, righte-of-way, southerms, beases and restrictions of recent or otherwise legally established which may not be necessarily above hereon. Bearings are oriented to North by GPS observations and tron pins No. of Control of Cont indicated (set) are 5/8" x 30" from rebars with an orange plastic cap stamped "EMLER 7760". Documents used were plats of local surveys, deed volumes and pages as shown hereon. 21.843 Total Acres (3) Denotes 5/8" x 30" irun pin (set) "EMLER 7760" Denotes stone morament (found) Control of the Control of Control 1310.T Southwest Quarter of Section 9, Township 10, Ronge 13, Brush Creek Township, Muskingum County, Ohio. Prepared By WARD & EMILER SURVEYING, INC. 113 Third Street S.E. ), the nudersigned, do herrby state that this plat is true said correct to the best of nayboowledge and belief. L-mailt westervey@adelphia.net New Philadelphia, Obio 44663 Phone: (339) 364-3866 Fax: (330) 364-1107 8 Sam Charles & J.J. DETWEILER ENTERPRISES, INC. **BUSH FARM** Plat of Shrvey Revised July 26, 2007 May 2007 J/DBUSH4 8 Date Surveyed: Locations 高麗

This property is subject to all legal highways, rights-of-way, easements, heaves and restrictions of record or otherwise legally established which may not be necessarily shown hereon.

## APPROVED MINOR LOT SPLIT ONLY MUSKINGUM COUNTY PLANNING COMMISSION DIRECTOR

Bale Fee Paid



Plat of Survey for J.J. DETWEILER ENTERPRISES, INC. BUSH FARM

Location:

Southwest Quarter of Section 9, Township 10, Range 13, Brush Creek Township, Muskingum County, Ohio.

Date Surveyed:

May 2007 Revised July 26, 2007

File ID:

**JJDBUSHS** 


Prepared By WARD & EMLER SURVEYING, INC. 113 Third Street S.E. New Philadelphia, Ohio 44663 Phone: (330) 364-5866

Fax: (330) 364-1107
Fax: (330) 364-1107

Enxail: wesurvey@adelphia.net

I, the undersigned, do heraby visite that this plat is true and correct to the

NOT RECORDABLE 161y 24, 2007



- Denotes 5/8" x 30" iron pin (set) "EMLER 7760"
- Denotes stone monument (found)

Bearings are oriented to North by GPS observations and iron pins indicated (set) are 5/8" x 30" iron rebars with an arange plastic cap stamped "EMLER 7760".

Documents used were plats of local surveys, deed volumes and pages as shown hereon.

This property is located in Zone X as shown on Community Paset #390425-0175 C effective date June 3, 1968 of the Flood Insurance Rice Maps and is not in a special flood bazard area as determined by graphic methods only.

# APPROVED MINOR LOT SPLIT ONLY MUSKINGUM COUNTY PLANNING COMMISSION DIRECTOR Date TEACT STREET



Plat of Survey
For

J.J. DETWEILER ENTERPRISES, INC.
BUSH FARM

Location:

Southwest Quarter of Section 9, Township 10, Range 13, Brush Creek
Township, Muskingum County, Ohio.

Date Surveyed:

May 2007 Revised July 26, 2007

File ID:


JJDBUSH5

Prepared By
WARD & EMLER SURVEYING, INC.
113 Third Street S.E.
New Philadelphia, Ohlo 44663
Phone: (330) 364-5866

Phone: (330) 364-5866 Fax: (330) 364-1107 (1) [1] Egnail: wesurvey@adelphia.net

I, the undersigned, do hereby state that this part is zeue and correct to the

NOT RECORDABLE Day 26, 2007



- Denotes 5/8" x 30" iron pin (set) "EMLER 7760"
- □ Denotes stone monument (found)

Bearings are oriented to North by GPS observations and iron pins indicated (set) are 5/8" x 30" iron rebars with an orange plastic cap stamped "EMLER 7760".

Documents used were plats of local surveys, deed volumes and pages as shown hereon.

This property is located in Zone X as shown on Community Panel #390425 0175 C effective date June 3, 1988 of the Flood Insurance Rate Plagu and is not in a special flood hazard area as determined by graphic methods only.