




Except as specifically stated or shown on this plat, this survey does not purport to reflect any of the following which may be applicable to the subject real estate: Easements, other than possible easements that were visible at the time of making of this survey; building setback lines; restrictive covenants; subdivision restrictions; zoning or other land-use regulations, and any other facts that an accurate and current title search may disclose.

Surveyor has made no investigation or independent search for easements of record, encumbrances, restrictive covenants, ownership title evidence, or any other facts that an accurate and current title search may disclose.

Bearings are based on the west line of lot 5 of Underwoods Addition, Bearing N 00° 26' 17" E.

Iron pins set are 5/8 inch rebar, 30 inches long, with plastic identification caps set flush with the ground.

NOTE:
This survey plat was created from deed records. No field survey was completed.

DESCRIPTION APPROVED
FOR AUDITORS TRANSFER
BY *[Signature]*
8-8-97

F. & L. HERSHBERGER
DR 1091, Page 586

NOTE:
This survey plat was created from deed records. No field survey was completed.

Part of the lands of
Fred & Lovina Hershberger,
OR 1091, Page 586

The JW Company 1218 St. Rt. 93 NE New Lexington, Ohio 43764 (614) 342-5131	
SURVEY FOR: <u>Fred Hershberger</u>	
● IRON PIN SET	DATE: <u>06/24/97</u>
○ IRON PIN FOUND	RANGE: <u>7W</u>
⊕ POST	TOWNSHIP: <u>1N</u>
▲ RAILROAD SPIKE SET	SECTION: <u>QUARTER TWP. 2</u>
△ RR SPIKE FOUND	POL. <u>TWP. FALLS</u>
○ STONE FOUND	COUNTY: <u>MUSKINGUM</u>
• TREE	SCALE: <u>1" = 150'</u>
• POINT	STATE OF <u>OHIO</u>
RONALD M. MERCKLE OHIO REG. SURVEYOR NO. 6473	THOMAS S. WILSON OHIO REG. SURVEYOR NO. 6465

NOT RECORDED