## 29-20-51-14-001 ADONTISS NA

## DESCRIPTION OF SURVEY FOR JOHN RIDGEWAY

**JOB#660** 

Situated in the State of Ohio, County of Muskingum, Township of Jackson:

Being part of the West Half of Lot #7, of Quarter Township #1, Township #3, Range #9, of the US Military District, being all the remaining portion of John W. Cannon and Sally Cannon property as described in deed reference Deed Book Volume 936, , Page 239 of said county's deed records, also being all of Muskingum County Auditor's Parcel Number 29-29-20-51-14-001, and more particularly described as follows;

Commencing at the Southeast corner of the West Half of Lot #7; thence N 03 05 20 W 265.00 feet (by deed) along the East line of said West Half of Lot #7 to an iron pin (found) at the Northeast corner of the D. Myers property as described in deed reference Deed Book Volume 1004, Page 357, also being the place of beginning for the property herein intended to be described;

- #1- thence S 82 34 25 W 315.06 feet along the North line of said Myers
  property to the center of West Carlisle Road (County Road #94), passing
  an iron pin (set) at 275.07 feet;
  #2- thence N 47 00 55 W 103.23 feet along the center of said road and
- #2- thence N 47 00 55 W 103.23 feet along the center of said road and along a line of the C. Miller property as described in deed reference Deed Book Volume 1007, Page 456 to the Southeast corner of the D Masholder property as described in deed reference Deed Book Volume 1054, Page 573;
- #3- thence N 04 21 25 E 38.58 feet leaving said road and along the East line of said Volume 1054, Page 573 to an iron pin (found) at a corner of a second property owned by D. Masholder as described in deed reference Deed Book Volume 1059, Page 478; #4- thence N 44 17 55 E 125.22 feet along a line of said Volume 1059, Page
- #4- thence N 44 17 55 E 125.22 feet along a line of said Volume 1059, Page 478 to an iron pin (set replacing an iron pin found disturbed) at a corner of said Masholder property;
- #5- thence N 01 43 40 W 499.75 feet along the East line of said Masholder property to the North line of said Cannon property being the Northeast corner of said Volume 1059, Page 478, from which an iron pin (found) for reference bears N 01 43 40 W 0.67 feet, also for reference an iron pipe (found) at the common Northwest corner of said original Cannon property and Masholder property bears S 86 48 50 W 163.70 feet;
- #6- thence N 86 48 50 E 277.62 feet along the North line of said Cannon property also being a line of the J Priest property as described in deed reference Deed Book Volume 952, Page 87 to an iron pipe (found) at the Northeast corner of said Cannon property and corner of said Priest property also being on the East line of said West Half of Lot #7;
- #7- thence S 03 00 50 E 673.63 feet along the East line of said West Half and East line of said Cannon property to the place of beginning, containing 4.75 acres.

The bearings within the description are based on the South line of the John Cannon property as described in deed reference Deed Book Volume 936, Page 239. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on July 5, 1995, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.



