## Property Survey Split for Benjamin T. Jr. and Rebecca Moore Tract Five

Being a part of the Quarter Township I, Township 2 North, Range 9 West, United States Military Lands, and more particularly described as follows:

Beginning for reference at an iron pin found at the Northeast corner of Lot 4, of the Subdivision of Thomas Wills Land, as depicted in Plat Book A-O, page 114, of the Muskingum County Records. Thence along the north line of said Lot 4 North 90 degrees 00 minutes 00 seconds West, 127.16 to an iron pin found at the southeast corner of lands presently owned by Benjamin T. Jr., and Rebecca Moore (DR 813-314); thence along the west line of lands presently owned by L. A. Prior et. al. (DR 1157-577), North 00 degrees 43 minutes 00 seconds West, 370.00 feet to an iron pin found on the edge of Prior Road (Twp. Rd. 406); thence continuing along said line North 00 degrees 43 minutes 00 seconds West, 230.47 feet to a point, and the principal place of beginning; thence leaving said west line and through said Moore lands the following three courses: 1.) North 90 degrees 00 minutes 00 seconds West, 378.00 feet to an iron pin set, passing an iron pin set at 20.95 feet; 2.) North 00 degrees 43 minutes 00 seconds West, 128.00 feet to an iron pin set; 3.) North 90 degrees 00 minutes 00 seconds East, 378.00 feet to a point in said Prior Road, and on said west line of Prior lands, passing an iron pin set at 362.97 feet; thence along said west line South 00 degrees 43 minutes 00 seconds East, 128.00 feet, to the principal place of beginning, containing 1.11 acres more or less.

Subject to all legal right of ways, and applicable easements written or implied.

Bearings are based on the north line of Thomas Wills Subdivision being North 90 degrees West as depicted on plat of said lands in Plat Book A-O, page 114, of the Muskingum County Records.

This survey is based on a field survey completed March 9, 2004 by Jack D. Newcome, Reg. No. 7321.

Part of Parcel No.: 35-35-10-71-25-000 +-1.11 Acres

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER BY 17-19-1 00-4



00,43,00,

00°43'00"W

230,47

Ė

Centerline of Prior Rd.(Twb

# Survey For Benjamin T. Jr. and Rebecca Moore 6725 Prior Road Nashport, Ohio 43830

### SITUATED IN

State of Ohio, County of Muskingum, Township of Licking, and being part of Quarter Township 1, Township 2 North, Range 9 West, U.S.M.L.

00°43'00"₩

9.T. Jr., and R. Moore DR 813-314

\$ 89\*59\*58\*E 15.03' \

50'89, \_\_\_ N 80,00,00,E

N 90°00'00"E 362.97'

# REFERENCES

DR 819-314 DR 1021-169 DR 834-331 DR 1130-479 DR 1122-579 Tax Map 35-10 Tax Map 35-44 PLBk A-0 Pg.114

Benjamin T. Jr. and Rebecca Moore DR 813-314 +-1.11 Acres Tract Five

N 90°00'00"E

357.00

B.T. Jr., and R. Moore DR 813-314

L. A. Prior et. al. DR 1157-577

Note: Right of Way width of Prior Road is unknown as per information from Muskingum County Engineers Office.

> DESCRIPTION APPROVED FOR AUDITOR'S THANSFER BY

3-19-2004

B.T. Jr., and R. Moore DR 813-314

Lot Split Approved

# LEGEND

B.T. Jr., and R. Moore

DR 813-314

- △ Haritroed Spike Set
- lron Pin Found
- B Stone Found
- Axis Found
  Iron Pipe Found.
- ▲ Builroed Spike Found
- Streen Pips Set., 5/67 reber
- Manument found

152'19, N 30,00,00,M

-1551.58 to stone found

# BASIS OF BEARINGS

Bearings are based on the north line of Thomas Wills Subdivision being North 90 degrees West, as depicted on plat of said lands in Plat Book A-O, Page 114, of the Muskingum County Records.

PARCEL NO.

Part of: 35-35-10-71-25-000

DR HEZERALI OF OATO JACK D. NEWCOME: C

378,00

F. and ML

RESTING

Northeast Corner of Lot 4, of Subdivision of Thomas Wille land, as depicted in Plat Book A-0 Page 114.


> OFFICE COPY VOT BEATA

Jack D. Housens UABlas

Reg. Surveyor No. 7821

#### SITUATED IN:

State of Ohio. County of Muskingum, Township of Licking, and being part of the Southeast Quarter of Quarter Township One, Township 2, Range 9, United States Military Lands, and the north line of lands presently owned by Benjamin and Rebecca Moore(DR 813-314), Parcel One.



NOTE: Stone found approximately 4 inches by 12 inches, with the top damaged from farm equipment and leaning toward the north. I straightened the stone to a vertical position and placed a drill hole in the center to reference my survey. This stone was called for in the original deed of Moore's land and the original deed of Hilty's land.

### REFERENCES

DR 813-314 OR 1650-752 OR 1629-808 OR 1850-378 Wetland Retracement Survey by Steven J. Hyde

Property Line Location for Ben Moore

Hilty LLC, OR 1850-378

Overlap Area = +- 0.57 Acres

Benjamin and Rebecca Moore

DR 813-314

Surveyor's Report

The four iron pins found as shown on the plat were used to re-establish the survey line of Hilty LLC, as per Donaker's survey. The northern most stone on the southeast corner was used per Donaker's survey information. But the southern most stone was the one clearly marked in the field and witnessed by a plastic electric fence post, as were two of the other pins found set by Donaker. The witness fence post appears to have been set in error by the south stone, rather than the north stone which was used for the survey. Donaker's survey plat does not show two stones found, only one, and indicates the stone found is the adjoiner's southwest corner.

The original deeds for both properties call for a stone on the southwestern corner, and as depicted was found. The west line of the property was called to be "north to the center of the road". Using the deed distance (394.02 ft.), and the centerline of the existing road, I retraced the survey. The survey line of Donaker's survey is not the centerline of the existing road, as called for in the original deed.

A Wetland Retracement Survey was performed by Hyde-Leroy land Surveying Inc. and their plat indicates they used Donaker,s survey, but aerial targets found in the field, indicate they used the stone to the south on the east(because it was witnessed), and the iron pin on the west, creating even more of an overlap, the main concern of my client was his pond, and per my survey, it is no longer part of the Hilty property.

S 84°47'40"W 1323.16

N 85°57'57"E 1323.79' (Rec. Dist. 1323.30')

#### BASIS OF BEARINGS

Bearings are based on a previous surveys of adjoining properties by E. R. Donaker as described in OR 1850-378, OR 1650-752, and 1629-808.

> W. N. Bradley DR 896-356

NOTE: The the most northerly found stone is approximately 7 inches square and the top has been damaged due to farm equipment. An old iron pin was found right beside the east side of the stone with old survey ribbon on parole evidence from Ben Moore. Since the top was damaged, I placed a drill hole in the top and center to reference my survey.

The most southerly found stone is

OF NEWCOME **EXEMPT FROM** PLANNING, COMMISSION

N '00°45' 19"E

PARCEL NO.

North line of Parcel No. 35-35-10-71-25-000 South line of Parcel No.

35-35-10-71-16-000

LEGEND

Railroad Spike Set

Iron Pin Found

Iron Pipe Found

Monument Found

Railroad Spike Found

Iron Pin Set. 5/8" rebar

Stone Found

Arie Found

V. W. Prior OR 1603-942

attached. I believe this to be the corner based

approximately 4 inches by 10 inches with a chiseled cross, and a plastic electric fence post was beside it as a witness.

> Newcome Surveying Company 6515 Ballard Road Nashport, Ohio 740-452-5796