44-36-01-72

2600 HENNESSEY LIC

Vista View Golf Course 153.905 Ac. Part of Parcel No. 44-36-01-72-000 Part of Parcel No. 44-38-01-06-000 Part of Parcei No. 44-38-01-06-001

Situated in the State of Ohio, County of Muskingum, Township of Muskingum; Being a part of the Southeast and Southwest Quarters of Section 19, Township . Two (2), Range Eight (8) of the United States Military Lands and part of the property owned by Vista View Village, Inc. and Recorded in Volume 643, Page 10 and part of Volume 653, Page 304 of the Muskingum County Deed Records bounded and described as follows:

Beginning at a stone found at the southeast corner of said southeast quarter of section 19; thence N 87° 39' 32" W (the base of bearings for this description is State Plane Grid from a Solar Observation) along the south line of said southeast quarter and the north line of properties owned by John Bunting (Vol. 637, pg. 173), Roger and Party Bronker (Vol. 995, pg. 585), Chris E. Cover (Vol. 1067, pg. 633) and Harold and Juanita Covert (Vol. 1072, pg. 82) 2696.74 feet to an iron pin found capped R.L. Daniels No. 5410 at the southwest corner of said southeast quarter of section 19; thence N 2º 10' 53" E along the west line of said quarter and along the east line of property owned by Bernice M. DeLong (Vol. 523, pg. 175) 573.00 feet to a 3/4" pipe found; thence N 87º 54' 24" W and passing into the southwest quarter of said section 19 and along the north line of said DeLong property 2341.30 feet to a 3/4" iron pipe found: thence N 2º 05' 22" E along the east line of property owned by S.M.V. Holding Group (Vol. 1088, pg. 84) 310.82 feet to a 3/4" pipe found; thence N 00° 05' 56" W along the east line of a 3.05 acre parcel owned by Robert Todd (Vol. 1160, pg. 755) 102,42 feet to an iron pin set; thence N 12° 42' 20" E along the east line of said 3.05 acre parcel 178.69 feet to an iron pin set, thence N 00° 25' 07" W along the east line of said parcel 181.63 feet to an iron pin set; thence N 1º 31' 08" W along the east line of a 0.125 acre parcel owned by Timothy Todd (Vol. 1154, pg. 211) 79.08 feet to an iron pin set; thence N 19º 41' 15" E along the east line of said parcel 89.29 feet to an iron pin set; thence N 18º 28' 04" E along the east line of a 3.675 acre parcel owned by Vista View Village, Inc. (Vol. 653, pg. 304) 219.02 feet to an iron pin set; thence N 19° 52' 06" E 167.77 feet to an iron pin set at the southeast corner of Lot 1 of Vista View Village Subdivision (P.B. 13, pg. 76); thence along the easterly line of Lot 2 on a curve to the left having a radius of 349.69 feet (the chord of which bears N 48° 35' 57" E 54.94) an arc distance of 55.00 feet to a point; thence N 44° 04' 35" E 175.00 feet to the southeasterly corner of Lot 3; thence on a curve to the right having a radius of 77.05 feet (the chord of which bears N 68º 04' 49" E 62.68 feet) an arc distance of 64.55 feet to the southeast corner of Lot 4; thence S 87º 55' 09" E 73.30 feet to the southeast corner of Lot 5; thence on a curve to the left having a radius of 212.02 feet (the chord of which bears N 62° 01' 50" E 212.34 feet) an arc distance of 222.40 feet to a 3/4" iron pipe found at the southeast corner of Lot

6 of said Vista View Subdivision; thence S 32° 41' 20" E along the westerly line of property owned by Doc Con INV, LTD

(Vol. 1145, pg. 192) 9.73 feet to an iron pin set in a creek; thence along the easterly line of said property and along said creek N 57º 29' 25" E 560.10 feet to a point on the south line of Lot 21 of said Vista View Subdivision (P.B. 13, pg. 76); thence S 87º 30' 36" E along the south line of said Subdivision 160 feet to an iron pin set at the southeast corner of Lot 22; thence \$ 87° 31' 02" E along the south line of said Subdivision 729.67 feet to a 3/4" pipe found on the south line of Lot 29 and the northwest corner of Lot 31; thence on a curve to the right having a radius of 311.57 feet (the chord of which bears S 38° 27' 34" W 366.67 feet) an arc distance of 392.03 feet to an iron pin found; thence S 74° 30' 16" W along said Subdivision 649.61 feet to an iron pin found; thence on a curve to the left having a radius of 899.54 feet (the chord of which bears \$ 41° 29' 00" W 980.40 feet) an arc distance of 1036.86 feet to an iron pin found at the southwest corner of Lot 50; thence S 8º 30' 12" W 116,49 feet to an iron pin set; thence along the arc of Lots 52, 53, 54, 55 and 56 on a curve to the left having a radius of 199.83 feet (the chord of which bears S 81° 30' 47" E 349.62 feet an arc distance of 829.95 feet to an iron pin found th the southeast corner of Lot 57; thence N 8º 30' 12" E along the east line of Lot 57 and 58 a distance of 116.49 feet to an iron pin found; thence on a curve to the right having a radius of 550.12 feet (the chord of which bears N 41º 29' 48" E 599.36 feet) an arc distance of 633.84 feet to an iron pin found; thence N 74° 30' 15" E along the southeasterly line of said Vista View Subdivision 649,60 feet to an iron pin set on the west line of Lot 71 and the east line of Hennessey Drive; thence S 15° 29' 44" E along the east line of said Drive 10.75 feet to an iron pin set at the southwest corner of Lot 71; thence on a curve to the left having a radius 672.55 feet (the chord of which bears N 38° 29' 32" E 790.86 feet an arc distance of 845.44 feet to an iron pin found on the east line of Lot 76 of said Vista View Subdivision, said pin bears S 2º 05' 26" W 200.23 feet from a 3/4" pipe in Vista View Drive at the center of section 19; thence -S 2° 05' 26" W along the east line of the southwest quarter of section 19 and the west line of the Green at Vista Subdivision (P.B. 17, pg. 104-107) a distance of 793.00 feet to an iron pin set; thence crossing into the southeast quarter of section 19 and following the boundary of Vista View Golf Course the following 15 courses and distances: 1 - S 85° 27' 14" E 114.91 feet to an ironain set

- 2 S 25° 49' 09" E 440.10 feet to an iron pin set
- 3 S 41º 46' 44" E 582.23 feet to an iron pin set
- 4 S 61° 57 01" E 348.09 feet to an iron pin set
- 5 S 70° 56' 08" E 712.93 feet to an iron pin set
- 6 N 65° 30' 08" E 154.08 feet to an iron pin set
- 7 N 00° 26' 53" E 166.45 feet to an iron pin set

8 - N 34° 38' 43" W 645.60 feet to an iron pin set

9 - N 64° 29' 02" W 335.81 feet to an iron pin set

10 - N 45° 53' 01" W 542.72 feet to an iron pin set

11 - N 00° 49' 42" E 367.51 feet to an iron pin set

12 - S 80° 15' 30" E 636.18 feet to an iron pin set

13 - S 64° 56' 12" E 638.41 feet to an iron pin set

14 - S 24º 33' 35" E 999.07 feet to an iron pin set


15 - S 72° 10' 42" E 287.12 feet to an iron pin set on the east line of said southeast quarter of section 19; thence S 1° 51' 55" W along the east line of said quarter and the west line of property owned by Brian and Rae Ann Jasper (Vol. 1147, pg. 677) a distance of 835.62 feet to the true place of beginning containing One-hundred-fifty-three and nine-hundred-five thousandths (153.905) acres of which 72.803 acres are in the southwest quarter of section 19 and part of Autilitors Parcel No. 44-36-01-72-000 and 81.102 acres is in the southeast quarter of section 19, 1.452 acres and 17.114 acres is part of Auditors Parcel No. 44-38-01-06-000 and 62.536 acres are part of Auditors Parcel No. 44-38-01-06-001.

Subject to all legal right-of-ways and easements on record.

All iron pins set are 5/8" x 30" rebar capped Graves No. 5792.

This description of Field Survey March 30, 2001, by Richard Max Graves, Reportered Starty, ORY 5792.

-10-2001



44-38-01-06 NA

Vista View Village Vol. 643, Pg. 10 Part of Parcel No. 44-38-01-06-000

Situated in the State of Ohio, County of Muskingum, Township of Muskingum: Being a part of the Southeast Quarter of Section Nineteen (19), Township Two (2), Range Eight (8) of the United States Military Lands and part of the second parcel of Volume 643, Page 10 of land in the name of Vista View Village bounded and described as follows:


Commencing at an iron pin found at the northeast corner of said southeast quarter of section 19; thence N 87º 12' 24" W (the base of bearings for this description is true north by an observation of the sun) along the north line of said southeast quarter of section 19 a distance of 265.00 feet to a point in Vista View Drive at the true place of beginning for the following described parcel; thence S 2º 12' 16" W along the west line of property owned by Ohio Power Company (670, Pg. 135) a distance of 385.60 feet to an iron pin found capped Walton # 7675 and passing through an iron pin set at 20.00 feet; thence N 20° 37' 08" W along the northeasterly line of property owned by Layman and Shirley Bailey (Vol. 1141, Pg. 8) a distance of 182.33 feet to an axle found; thence N 1º 17' 41" E along the east line of property owned by David Sheets (Vol. 791, Pg.147) a distance of 218.34 feet to a point in said Vista View Drive on the north line of said southeast quarter of section 19 and passing through an iron pin set at 134.85 feet and through an axie found at 200.85 feet; thence S 87º 12' 24" E along the north line of said quarter and along Vista View Drive 74.19 feet to the true place of beginning containing Fifty-hundredths of an acre.


Part of Parcel No. 44-38-01-06-000.

Subject to all legal right-of-ways and easements on record.

All iron pins set are 5/8" x 30" rebar capped No. 5792.

This description was written from Oield Survey made April 12, 2002 by Richard Max Graves, Registered Surveyor, Nover All Control Approved FOR AUDODRY TRANSFER BAX GRAVES 5-5792





SNR