BOWMAN & ASSOCIATES 59 SECOND STREET FRAZEYSBURG, OHIO 43822 PH./FAX (614) 828-2204

SURVEY DESCRIPTION FOR Ronald Pryor

PART OF AUDITORS PARCEL #44-48-01-18-000

Situated in section #22, T-2-N, R-8-W, U.S.M.L., Muskingum Township, Muskingum County, Ohio. Being all the lands of Robert Wilkinson, conveyed in deed book 553 page 968 of the Muskingum County deed records, which lie south of Township Road #149 and west of the centerline of State Route 60, being more particularly described as follows:

Beginning at a stone found marking the Southwest corner of section #22;

- thence, N.01 34'52 E. a distance of 340.58 feet along the west line of section #22 to a stone found at the Southwest corner of the Baxter Cemetery (41/143), said stone is located 20.0 feet east of an existing corner post;
- thence, S.83 19'00 E. a distance of 179.48 feet along the South line of said Cemetery lands to a found stone;
- thence, N.06°33'35"E. a distance of 93.13 feet along said cemetery lands to to a found stone;
- thence, N.29°25'00"W. a distance of 148.17 feet along said cemetery lands to to a set iron pipe;
- thence, W.55°25'00"W. a distance of 63.53 feet along said cemetery lands to to a set iron pipe;
- thence, N.74°39'00"W. a distance of 13.53 feet along said cemetery lands to to a set iron pipe, on the Southeast corner of the lands, now or formerly, owned by R. Graves (1085/111);
- thence, M.06°50'00°E. a distance of 623.70 feet along said Graves lands to a set iron pipe;
- thence, N.26'00'00"E. a distance of 126.29 feet along said Graves lands to a point in the center of Township Road #149 (Carnation Road), passing a set iron pipe at 100.32 feet;
- thence, S.62°05'55"B. a distance of 849.13 feet along said road to a point in the center of State Route #60 (Frazeysburg Road);
- thence, S.09°55'15"E. a distance of 340.60 feet along the centerline of said State Route to a point;
- thence, S.75°27'12"W. a distance of 272.65 feet leaving said State Route and going along the lands, now or formerly, owned by R.& K. Pryor (997/521) to a found iron pin, passing a set iron plpe at 30.00 feet;
- thence, S.18°48'18°E. a distance of 166.24 feet along said Pryor lands to a found iton pin;
- thence, N.77°23'06"E. a distance of 112.42 feet along said Pryor lands to a found iron pin;
- thence, \$.67°14'49"E. a distance of 24.95 feet along said Pryor lands to a found iron pin;
- thence, S.86'40'17*B. a distance of 115.87 feet along said Pryor lands to a a point in the center of State Route #60, passing a found iron pin at 85.19 feet;
- thence, S.09°55'15"E. a distance of 329.31 feet along the center of said State Route to a point;

Pryor cont.

thence, on a curve to the right a distance of 97.88 feet with a radius of 2,864.93 feet whose chord bears S.08°37'06"E. a distance of 97.86 feet along said State Route to a point on the South line of Section #22:

thence, N.87°00'00"W. a distance of 1,109.84 feet along said section line to the point of beginning, passing a set iron pipe at 30.00 feet;

The above described purcel contains 23.481 acres, more or less, and is subject to all legal easements and right of ways. All set iron pipes are $3/4" \times 30"$ pipes with plastic I.D. caps. North is based upon the South line of section #22 bearing N.87°00'00"W.

Description was prepared from an actual survey by Bowman & Associates, Stephen M. Bowman, P.S.#7135. February 1, 1995

OFFICE COPY NOT RECORDABLE DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

2-2-95

