3505 DALLINGTON DR.

Larry Tipton 5/28/96

Situated in the State of Chio, County of Muskingum, Township of Newton, Township 15, Range 14, Section 11. Being Lots 25, 26, 27, & 28, of Burton's Addition to Darlington and South Half of vacated 16 foot alley, Plat Book 5, Pages 44 & 45, bounded and described as follows:

Beginning at an iron pin found at the Southeast corner of Lot 25; thence South 87 26' 00" West along Darlington Drive 200.00 feet to an iron pin set, from which iron pins found bear South 87 26' 00" West 117.78 and 232.75 feet; thence North 2 34' 00" West along the West line of Lot 28 158.00 feet to the center of a vacated 16 foot alley; thence along center of said vacated 16 foot alley North 87 26' 00" East 200.00 feet to an iron pin set; thence South 2 34' 00" East along the East side of Lot 25 158.00 feet to the place of beginning, containing 0.725 acres more or less.

Bearings are based on the South line of lots along Darlington Drive bearing South 87° 25' 00" West.

Being all of Auditor's Parcel Numbers 47-30-01-33-000

47--30--01--32--000

47-30-01-31-000

47--30--01 -- 30--000

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.


Reference: Vol. 662, Page 193 and Vol. 984, Page 269.

ov & Description By:

NOTRECORDABLE

R. L. Daniels Registered Surveyor No. 5410 FOR AUDITORS TRANSFER

5-31-%





		N 87°26'00"E			Center C Alley 	4 16 Yacated
	00.85/	7 5 0 .00 8 8	-5 0. 00	-50.00	50.00	<u> </u>
	12034'00'W!	. 28 . 58	27	26	Ω 50 53,00,€	58.00 00
	<i>γ2°</i>	(30) (30)	(31)	(3Z)	33	
0 14,97 0 -	117,78 15	50.00	50.00 5 87°2	50.00 6'00'W	50.00	16'

O Iron Pins Found

• Iron Pins Set No. 5 Reing Bars 30'Lg Plastic ID Caps.

Parcel Nos 47-30-01-33-000 "" 1 1 32-000 " " " 31-000 " " " 30-000

DESCRIPTION APPROVED FOR AUDITORS TRANSFER

5-21-26

Survey of Lots 25,26,27428
Of Darling ton Burton's Add.
P.B.5
Muskin OFFICE COPY
New to NOTHE CORDABLE
N.E. Q to Reg. Sureyor
No. 5410