Ronald Spring

Situated in the State of Ohio, County of Muskingum, Township of Newton, Township 15, Range 14, part of Section 26, bounded and described as follows:

Being part of Ronald Spring O.R. Vol. 1128 , Page 235 , Parcel No. 47-94-26-14 -001

Commencing at an iron pin found at the Southwest Corner of the Southwest Quarter of Section 26; Thence North 00°21'15" East 2106.17 feet to an iron pin at the Northwest Corner of the original Mary Spring Farm; Thence South 41°55'27" East 1448.07 feet to an Iron pin set the place of beginning; Thence North 77°16'42" East 510.14 feet to an Iron pin set; Thence South 3°49'53" East 293.71 feet to an Iron pin set on the Lawrence Spring North line; Thence along Lawrence Spring O.R. Vol. 128, Page 634, the next four courses and distances: South 67°36'22" West 71.00 feet to an Iron pin found, South 57°47'44" West 228.43 feet to an Iron pin found, North 84°10'45" West 383.30 feet to an Iron pin found, and North 43°26'50" West 106.30 feet to an Iron pin set; Thence leaving Lawrence Spring's line North 42°34'31" East 289.87 feet to the place of beginning containing 4.77 acres more or less:

Bearings are based on the West line of the Southwest Quarter of Section 26 bearing North 00°21'15" East.

Above description is based on a survey by R.L. Daniels Registered Surveyor No. 5410, March 27, 2001, and is intended for legal transfer of property described and does not intend to describe any or all easements of record encroachments unless otherwise indicated.

Iron pins set are No. 5 reinf. bars 30 inches long with plastic I.O. caps,

Ref. O.R. Vol. 1128, Page 235.

Also the right to Use existing 30 footdrive for

access to Ransbottom Road.

OMFREE COPYMA NOT RECORDABLE

3-30-2001

